



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-10-01
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-14
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-02
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	21
Total items failed	1

MOT #11	2024-01-23 09:57
MOT test number	692603575690
Result	✓ Passed
Next expiry date	2025-02-02

MOT #10	2023-01-05 08:46
MOT test number	256457712485
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #9	2022-02-03 12:59
MOT test number	139977838281
Result	✓ Passed

MOT #8	2021-09-21 13:48
MOT test number	100573389871
Result	✓ Passed

**MOT #7** 2020-08-20 08:57**MOT test number** 273385987792**Result** ✓ Passed**Advice** Offside Rear tyre tread misshapen**Advice** Nearside Rear tyre tread misshapen**MOT #6** 2019-09-04 14:39**MOT test number** 267270488765**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Undertray(s) fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 235/45/17 97W (5.2.3 (e))**Advice** Engine cover fitted obscuring some engine bay components**MOT #5** 2019-09-04 08:56**MOT test number** 582736208742**Result** ✗ Failed**Advice** Undertray(s) fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 235/45/17 97W (5.2.3 (e))**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Engine cover fitted obscuring some engine bay components**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2018-08-13 11:03**MOT test number** 311651618592**Result** ✓ Passed**Advice** UNDERTRAY(S) FITTED OBSCURING SOME UNDERSIDE COMPONENTS**Advice** ENGINE COVER FITTED OBSCURING SOME ENGINE BAY COMPONENTS**MOT #3** 2017-09-05 12:09**MOT test number** 214131722504**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit INNER TREAD (4.1.E.1)**Advice** UNDERTRAY(S) FITTED OBSCURING SOME UNDERSIDE COMPONENTS**Advice** Nearside Front Tyre worn close to the legal limit INNER TREAD 235/45/17 97W (4.1.E.1)**Advice** ENGINE COVER FITTED OBSCURING SOME ENGINE BAY COMPONENTS**Advice** Offside Front TYRE HAS A CUT BUT NOT ENOUGH TO MEET FAILURE REQUIREMENTS**MOT #2** 2016-10-05 09:36**MOT test number** 735152427141**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-09-22 12:33**MOT test number** 487167806421**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-19
Last registration	2024-01-23
Complete history	See info



Registration #1	2012-10-19	22 mi
Registration #2	2015-09-22	38.051 mi
Registration #3	2016-10-05	49.200 mi
Registration #4	2017-09-05	54.006 mi
Registration #5	2018-08-13	60.696 mi
Registration #6	2019-09-04	68.507 mi
Registration #7	2019-09-04	68.509 mi
Registration #8	2019-09-04	68.509 mi
Registration #9	2019-09-04	68.509 mi
Registration #10	2019-09-04	68.509 mi
Registration #11	2019-09-04	68.509 mi
Registration #12	2019-09-04	68.509 mi
Registration #13	2019-09-04	68.509 mi
Registration #14	2019-09-04	68.509 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1802 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1516 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1220500