





report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI HIGHLINE BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2016
Top speed	106 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

## Entry 2

Date	2023-11-05

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2022-07-24
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-06
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #7	2023-11-07 12:57
MOT test number	260283504792
Result	✓ Passed
Next expiry date	2024-11-06

MOT #6		2023-08-11 09:06
MOT test	number	397566514097
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2022-08-15 12:01
MOT test number	344430791144
Result	✓ Passed
MOT #4	2021-10-14 15:59
MOT test number	921467339491
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2020-07-31 09:24

**MOT test number** 729022966184

**Result** ✓ Passed

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-08-12 07:33

**MOT test number** 452264338252

**Result** ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view Chip in screen (3.2 (a) (i))

**Advice** Reg plate lights dim and flickering

MOT #1 2019-08-07 16:13

MOT test number 515403724311

Result X Failed

**Fail** Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Windscreen damaged but not adversely affecting driver's view Chip in screen (3.2 (a) (i))

**Advice** Reg plate lights dim and flickering

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	6 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra VOLKSWAGEN salvage check



**Category** 

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

# Owner history

Owner mistory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
********	
***************************************	
********	
***************************************	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-26
Last registration	2023-11-07
Complete history	See info



Registration #1	2016-07-26	21 mi
Registration #2	2019-08-07	40.763 mi
Registration #3	2019-08-12	40.764 mi
Registration #4	2020-07-31	50.596 mi
Registration #5	2021-10-14	58.283 mi
_		
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea 11.777 ea
•		11.77 m
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



## Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Wheel base	3 mm
Kerb weight	1594 kg
Max. allowed weight	2299 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	2
Number of axles	2
Engine number	DFSD084278