





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI STARTLINE
Colour	White
Year of manufacture	2016
Top speed	119 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-02-05

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-20
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #8		2024-03-06 14:16
MOT test	number	380084683006
Result		✓ Passed
Next expi	y date	2025-03-20
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice (5.2.3 (e))	Front Tyre worn close to legal limit/worn on edge both low on inner edges, ac	dvise tracking check.

MOT #7	2024-03-06 09:16
MOT test number	279340856309
Result	× Failed
Advice Front Tyre worn close to legal limit/worn on edge both low on inner edg (5.2.3 (e))	es, advise tracking check.
Fail Offside Front Suspension arm pin or bush excessively worn lower arm, rear	bush. (5.3.4 (a) (i))
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (kg))	D))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2023-03-21 12:41

MOT test number 957988852816

Result ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm, rear bush. (5.3.4 (a) (i))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #5 2023-03-21 10:09

MOT test number 691430671814

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm, rear bush. (5.3.4 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn lower arm, rear bush worn. (5.3.4 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #4 2022-03-14 11:48

MOT test number 766925802724

Result

Passed

MOT #3 2021-09-03 14:17

MOT test number 971086438266

Result ✓ Passed

MOT #2 2020-09-09 12:02

MOT test number 701442985040

Result
✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2019-08-23 08:22

MOT test number 849542789154

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Category

Type

Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.	· · · · · · · · · · · · · · · · · · ·	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow	
Plate changes See in this check if this VOLKSWAGEN had different number plates.	***************************************	
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
Plate changes See in this check if this VOLKSWAGEN had different number plates.		
See in this check if this VOLKSWAGEN had different number plates.		More info >
	Plate changes	
Plate since	See in this check if this VOLKSWAGEN had different number plates.	
Plate since	Number of plates	
UK UK	Current registration	UK UK
	Plate since	
Plate since	Current registration	UK UK
	Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company Date of agreement Agreement type Agreement term **Agreement number**

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-19
Last registration	2024-03-06
Complete history	See info



Registration #1	2016-09-19	15 mi
Registration #2	2019-08-23	55.842 mi
Registration #3	2020-09-09	76.301 mi
Registration #4	2021-09-03	93.473 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2065 mm
Height	1836 mm
Length	4878 mm
Wheel base	3006 mm
Kerb weight	1585 kg
Max. allowed weight	2333 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
CarChack co.uk	nago 12/1°

CarCheck.co.uk page 12/12

Engine number

DFSB089676