



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	MR2 T-BAR
Colour	Red
Year of manufacture	1992
Top speed	137 mph
0 - 60 mph	7.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	191 Nm at 4.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-22
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-09-21
<b>MOT pass rate</b>	82 %
<b>MOT passed</b>	9
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	6
<b>Total items failed</b>	4

<b>MOT #11</b>	2023-09-22 15:21
<b>MOT test number</b>	554639403313
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-09-21
<b>Minor</b>	Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

<b>MOT #10</b>	2022-09-16 14:43
<b>MOT test number</b>	476709699115
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2021-09-14 17:26
<b>MOT test number</b>	738266686534
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2020-10-28 08:57
<b>MOT test number</b>	176392541145
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2019-07-27 08:26
<b>MOT test number</b>	616829869656
<b>Result</b>	✓ Passed

**MOT #6** 2018-08-16 16:40**MOT test number** 276109678219**Result** ✓ Passed**Advice** Light under body corrosion**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2018-08-16 09:38**MOT test number** 284313326297**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))**Advice** Light under body corrosion**MOT #4** 2015-07-24 07:35**MOT test number** 958395205286**Result** ✓ Passed**MOT #3** 2015-07-24 07:35**MOT test number** 747755905267**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2009-04-06 15:43**MOT test number** 102876799421**Result** ✓ Passed



MOT #1	2006-08-05 10:38
MOT test number	863537716255
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
21 September 2024

Tax status		Valid until 1 July
Days left		63
MOT expiry date		21 September 2024
Full MOT history		<a href="#">See MOT history</a>




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	K866GCH
Plate since	2019-03-29
Current registration	K866GCH
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	1992-09-08
Last registration	2023-09-22
Complete history	<a href="#">See info</a>



Registration #1	1992-09-08	8 mi
Registration #2	2006-08-05	67.187 mi
Registration #3	2009-04-06	68.201 mi
Registration #4	2015-07-24	70.763 mi
Registration #5	2018-08-16	72.889 mi
Registration #6	2018-08-16	72.889 mi
Registration #7	2023-09-22	75.277 mi
Registration #8	2023-09-22	75.277 mi
Registration #9	2023-09-22	75.277 mi
Registration #10	2023-09-22	75.277 mi
Registration #11	2023-09-22	75.277 mi
Registration #12	2023-09-22	75.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1700 mm
Height	1240 mm
Length	4180 mm

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	3S9180803