





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 T-GDI SE NAV
Colour	Grey
Year of manufacture	2018
Top speed	117 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



YS18AOC report date: 2024-03-28

Internet history

-		-		1
п	L	ΓV	,	т.

Entry 1	
Date	2022-07-05
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-29
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #6	2023-06-20 08:56
MOT test number	709925594154
Result	✓ Passed
Next expiry date	2024-06-29
Advice Offside Rear Nail in tyre	

MOT #5	2023-06-20 08:56
MOT test number	749253367552
Result	★ Failed
Advice Offside Rear Nai	I in tyre
Pass with rectification	Windscreen washer provides insufficient washer liquid screen wash (3.5 (a))

MOT #4	2022-06-30 08:55
MOT test number	342603088899
Result	✓ Passed

MOT #3		2022-06-01 15:53
MOT test	number	967440750608
Result		✓ Passed
Advice inner edge	Offside Rear Tyre slightly damaged/cracking or perishing wearing on inr (5.2.3 (d) (ii))	ner edge/ also stepping on
Advice (ii))	Nearside Rear Tyre slightly damaged/cracking or perishing also wearing	on inner edge (5.2.3 (d)

CarCheck.co.uk page 3/11



YS18AOC report date: 2024-03-28

MOT #2 2022-06-01 12:21

MOT test number 327764905285

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing also wearing on inner edge (5.2.3 (d) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm below limit in places also bald on inner edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing wearing on inner edge/ also stepping on inner edge (5.2.3 (d) (ii))

MOT #1 2021-04-12 12:05

MOT test number 971856340902

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

e when miscory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

manage of the same	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Format maintration	
Carried region and	OK SIE
Plate since	
European respirations	NIE (
	IK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-27
Last registration	2023-06-20
Complete history	See info



Registration #1	2018-05-27	17 mi
Registration #2	2021-04-12	23.269 mi
Registration #3	2022-06-01	36.630 mi
Registration #4	2022-06-01	36.630 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11



YS18AOC report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	84%
Pedestrian	64%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1425 mm
Length	4455 mm
Wheel base	2650 mm
Kerb weight	1342 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles2Engine numberG3LCJP021400