






### General information

Make	HONDA
Model	ACCORD I-DTEC EX
Colour	Silver
Year of manufacture	2012
Top speed	129 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	162 g/km
CO2 label	G







## Internet history

Entry 1

Date

Pictures

2022-04-16

43

Listing price

View report









source: yesauto.com



## MOT history

MOT expiry date	2024-12-18
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	29
Total items failed	2

MOT #12		2023-11-28 14:49
MOT test	number	869187935374
Result		✓ Passed
Next expi	ry date	2024-12-18
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Shock absorbers has a reduced damping effect both rear shocks weak (5.3.	2 (d))
Advice	Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

# MOT #11 2022-12-19 10:25 MOT test number 703419434379 Result ✓ Passed Advice Nearside Rear Inner Tyre slightly damaged Slightly misshapen, advise replacement soon (5.2.3 (d) (ii)) Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #10	2022-01-07 16:12
MOT test number	727204958424
Result	✓ Passed
Advice Items removed from driver's view prior to test	



	B	6	1	V	Κ	Μ
r	ep	ort	dat	:e: 2	024-	03-28

MOT #9		2022-01-06 09:35
MOT test	number	609378642564
Result		🗙 Failed
Fail N	earside Rear Service brake excessively binding (1.2.1 (f))	
Advice	Items removed from driver's view prior to test	
Advice	Nearside Front tyre worn on far inner and outer edges	
Advice (ii))	Nearside Front Tyre slightly damaged/cracking or perishing especially the outer s	idewall (5.2.3 (d)
Advice	Offside Front tyre worn on far inner and outer edges	

MOT #8	2021-01-12 09:38
MOT test number	865825183457
Result	✓ Passed
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	

265994008414
✓ Passed

МОТ #6	2019-01-22 09:29
MOT test number	884672759488
Result	✓ Passed
Advice Items removed from driver's view prior to test	





MOT #5		2018-01-09 09:35
MOT test	number	983373986413
Result		Passed
Advice	Nearside rear tyre worn on far inner and outer edges	
Advice	Nearside Front Upper Exhaust has a minor leak of exhaust gases EGR fle	exi pipe blowing (7.1.2)
Advice	Offside rear tyre worn on far inner edge	
Advice	Items removed from driver's view prior to test	
MOT #4		2018-01-09 09:35
MOT test	number	679925415556

🗙 Failed
(7.1.2)

MOT #3		2017-01-17 15:03
MOT test	number	856654011080
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside rear tyre worn badly on far inner edge	
Advice	Items removed from driver's view prior to test	





MOT #2		2016-01-28 15:17
MOT test	number	960513742436
Result		✓ Passed
Advice	Items removed from drivers view prior to test	
MOT #1		2015-02-17 09:26
MOT test	number	188508345039
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Items removed from driver's view prior to test	
Notice	Engine covers fitted obscuring some components in the engine bay	



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 April 2025	<b>Expires:</b> 18 December 2024
Tax status	Valid until 1 April
Days left	338
MOT expiry date	18 December 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





# Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
*************	
********	
*******	
************	
********	
	More info >
Plate changes See in this check if this HONDA had different number plat	es
Number of plates	9
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-02-28
Last registration	2023-11-28
Complete history	See info



Registration #1	2012-02-28	13 mi
Registration #2	2015-02-17	25.271 mi
Registration #3	2016-01-28	38.878 mi
Registration #4	2017-01-17	51.921 mi
Registration #5	2018-01-09	64.499 mi
Registration #6	2018-01-09	64.499 mi
Registration #7	2019-01-22	75.476 mi
Registration #8		11.777 est
Registration #9		11.777 est
Registration #10		11.777 est
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		
-		





# Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1700 kg
Additional information	
Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22B13600895