



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D5 SE EU4
Colour	Silver
Year of manufacture	-
Top speed	140 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-01
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #15	2021-04-16 09:05
MOT test number	617363716611
Result	✓ Passed
Next expiry date	2022-04-22

MOT #14	2021-04-16 09:05
MOT test number	493035601038
Result	✗ Failed
Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #13	2020-04-02 09:59
MOT test number	226849909834
Result	✓ Passed
Advice Rear Tyre worn close to legal limit/worn on edge nearside / offside (5.2.3 (e))	

MOT #12	2019-04-18 13:30
MOT test number	219497141293
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge ns / os (5.2.3 (e))	
Advice Offside Rear Nail in tyre	

MOT #11	2018-04-23 12:47
MOT test number	108798194632
Result	✓ Passed

MOT #10	2017-03-22 13:49
MOT test number	481742630360
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin nearside / offside (3.5.1g)	

**MOT #9** 2016-04-06 15:59**MOT test number** 621995106409**Result** ✓ Passed**MOT #8** 2015-07-27 11:57**MOT test number** 686778505275**Result** ✓ Passed**MOT #7** 2014-07-23 12:57**MOT test number** 967604504252**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-07-22 15:18**MOT test number** 699403903238**Result** ✓ Passed**MOT #5** 2012-07-17 15:07**MOT test number** 635209992140**Result** ✓ Passed**Notice** Centre rear exhaust mount corroded**Notice** Undertray fitted not allowing full inspection of steering & suspension components**Notice** Rear exhaust mount corroded**MOT #4** 2011-07-27 11:27**MOT test number** 896518701212**Result** ✓ Passed**Notice** Rear exhaust mount corroded



MOT #3 2011-07-27 11:27

MOT test number 348558901265

Result ✗ Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Notice Rear exhaust mount corroded

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

MOT #2 2010-07-28 12:08

MOT test number 110699200264

Result ✓ Passed

MOT #1 2009-07-20 10:01

MOT test number 662811709259

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-07-28
Last registration	2021-04-16
Complete history	See info



Registration #1	2006-07-28	7 mi
Registration #2	2009-07-20	34.531 mi
Registration #3	2010-07-28	46.550 mi
Registration #4	2011-07-27	57.081 mi
Registration #5	2012-07-17	59.797 mi
Registration #6	2013-07-22	63.790 mi
Registration #7	2014-07-23	67.102 mi
Registration #8	2015-07-27	69.334 mi
Registration #9	2016-07-27	71.566 mi
Registration #10	2017-07-27	73.798 mi
Registration #11	2018-07-27	76.030 mi
Registration #12	2019-07-27	78.262 mi
Registration #13	2020-07-27	80.494 mi
Registration #14	2021-04-16	82.726 mi
Registration #15	2021-04-16	84.958 mi
Registration #16	2021-04-16	87.190 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Height	1428 mm
Length	4603 mm
Wheel base	2715 mm
Kerb weight	1519 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	417262