



PEUGEOT



SAILIOPD

report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-28
Pictures	3
Listing price	View report

Kevin M. 10 days

***** 5.0

Professional
Saw a car which was really quite clean for its age and stuff from the pictures ring the change at once sales had a lovely conversation for 20 mins instead of the 10 mins a returning customer even thought it was my first purchase I decided to leave a deposit to have the car deliver to my home in Knutsford the vehicle arrived on time from the logistics company that they use they were class top folks I was more than happy with the vehicle was as described signed the paper work and had a new vehicle. The sales rep rang me 5 days later via courtesy call and everything was brilliant. Customer service honestly 100% with this dealership.



Archie M. 1 day

***** 5.0

Absolutely brilliant service
Contacted regarding a car on Aut 10 days had heard and came back to talk to me. professional they were. From the first point of speaking to them to the end of the deal before driving away in my new car. Gave me my first day home before for a long time and made me feel like I was a customer. I later the car delivered and asked for the video which they provided me with all four of the sides and that when looking at it all they made me feel confident buying the car. The car came with 10 months WOT and that service history and they had all the documents in place. I have now bought the car and have had no issues with it whatsoever but I will have been given the chance of getting a new car with the car which I have been waiting. From the start. I cannot recommend these guys enough and have 100% will be buying there in the future I have had to buy another car.

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-29
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	39
Total items failed	4

MOT #14 2023-07-24 15:15

MOT test number 360351737733

Result ✓ Passed

Next expiry date 2024-07-29

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2023-07-24 15:15

MOT test number 827072928472

Result ✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2022-07-12 17:14**MOT test number** 853243140682**Result** ✓ Passed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #11** 2022-07-12 17:14**MOT test number** 572401315958**Result** ✗ Failed**Pass with rectification** Exhaust silencer insecure (8.1.1 (b) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2021-07-30 09:58**MOT test number** 170751652459**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9** 2020-11-05 15:36**MOT test number** 799037644184**Result** ✓ Passed**Advice** Sump porous oil leaks**Advice** Os mirror cowling broken**Advice** Osf brakedisc corroded on inner face**Advice** General vehicle condition corroded on underside brakepipes corroded

**MOT #8** 2020-11-04 13:01**MOT test number** 379232198934**Result** ✗ Failed**MAJOR** Offside Headlamp aim too high (4.1.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Osf brakedisc corroded on inner face**Advice** General vehicle condition corroded on underside brakepipes corroded**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Sump porous oil leaks**Advice** Os mirror cowling broken**MOT #7** 2019-04-27 14:53**MOT test number** 965817202060**Result** ✓ Passed**MOT #6** 2019-04-27 14:53**MOT test number** 521235285528**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #5**

2018-05-03 16:18

MOT test number

848317705513

Result

✓ Passed

Advice

Bonnet release insecure

Advice

Front registration plate delaminated but not likely to be misread (6.3.1d)

Advice

Oil leak

Advice

Hanger previously broken at the front of the rear silencer. hanger at the rear of the silencer is also about to break

MOT #4

2017-03-13 12:00

MOT test number

171670649973

Result

✓ Passed

Advice

Oil leak oil leak from engine

Advice

Rear registration plate faded but not likely to be misread (6.3.1d)

Advice

Under side coroshion

MOT #3

2017-03-13 12:00

MOT test number

259218135749

Result

✗ Failed

Advice

Under side coroshion

Advice

Oil leak oil leak from engine

Advice

Rear registration plate faded but not likely to be misread (6.3.1d)

Pass with rectification

Rear Exhaust system not adequately supported back box (7.1.1)



MOT #2	2015-03-05 12:00
MOT test number	168804765047
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2014-03-11 12:29
MOT test number	976410674066
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 July 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-19
Last registration	2023-07-24
Complete history	See info



Registration #1	2011-03-19	26 mi
Registration #2	2014-03-11	27.998 mi
Registration #3	2015-03-05	28.869 mi
Registration #4	2017-03-13	36.817 mi
Registration #5	2017-03-13	36.817 mi
Registration #6	2018-05-03	46.648 mi
Registration #7	2019-04-27	50.008 mi
Registration #8	2019-04-27	50.008 mi
Registration #9	2019-04-27	50.008 mi
Registration #10	2019-04-27	50.008 mi
Registration #11	2019-04-27	50.008 mi
Registration #12	2019-04-27	50.008 mi
Registration #13	2019-04-27	50.008 mi
Registration #14	2019-04-27	50.008 mi
Registration #15	2019-04-27	50.008 mi
Registration #16	2019-04-27	50.008 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FSX46458693