



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg





MOT history

MOT #9	2023-02-18 10:45
MOT test number	492283897905
Result	✓ Passed
Next expiry date	2024-02-17
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both sides front and rear (1.1.14 (a) (ii))

MOT #8	2023-02-09 16:23
MOT test number	820691097783
Result	✗ Failed
MAJOR	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both sides front and rear (1.1.14 (a) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
MAJOR	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #7	2022-01-11 15:27
MOT test number	292738351152
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2020-11-18 12:43
MOT test number	411048987893
Result	✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #5	2019-11-19 15:02
---------------	------------------

MOT test number	151024923216
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2019-11-18 16:06
---------------	------------------

MOT test number	729360463381
------------------------	--------------

Result	✗ Failed
---------------	----------

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #3	2019-03-16 15:05
---------------	------------------

MOT test number	484050813324
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2018-03-20 07:34
---------------	------------------

MOT test number	541849458770
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2017-03-14 08:40
---------------	------------------

MOT test number	134163730165
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-03-29
Last registration	2023-02-18
Complete history	See info



Registration #1	2014-03-29	8 mi
Registration #2	2017-03-14	20.928 mi
Registration #3	2018-03-20	29.885 mi
Registration #4	2019-03-16	36.524 mi
Registration #5	2019-11-18	88.965 mi
Registration #6	2020-05-20	95.377 mi
Registration #7	2020-05-20	95.377 mi
Registration #8	2020-05-20	95.377 mi
Registration #9	2020-05-20	95.377 mi
Registration #10	2023-02-18	95.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4312 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Engine number	D510601
---------------	---------