



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTi
Colour	Silver
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-12-13
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-08
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #8	2024-02-09 14:17
MOT test number	533111633174
Result	✓ Passed
Next expiry date	2025-02-08

MOT #7	2023-01-07 12:57
MOT test number	553598703290
Result	✓ Passed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #6	2022-01-19 10:34
MOT test number	204044587897
Result	✓ Passed

**MOT #5** 2022-01-17 16:30**MOT test number** 459566141982**Result** ✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement LOWER ARM - REAR BUSH. (5.3.4 (a) (i))

**Pass with rectification** Offside Front Headlamp aim too high DIP BEAM. (4.1.2 (a))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tread depth is low. (5.2.3 (e))

**Advice** Nearside rear road wheel is slightly damaged on its inner rim.

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #4** 2020-08-31 13:43**MOT test number** 204164723504**Result** ✓ Passed**MOT #3** 2019-09-26 12:59**MOT test number** 977577246547**Result** ✓ Passed

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #2** 2019-09-26 12:59**MOT test number** 819856609806**Result** ✗ Failed

**Pass with rectification** Offside Front Upper Suspension component damaged and seriously weakened top suspension mount (5.3.3 (b) (i))

**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #1** 2018-09-26 09:38**MOT test number** 549561458610**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
8 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	8 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	SH65KHX
Plate since	2019-06-29
Current registration	SH65KHX
Plate since	2019-06-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-30
Last registration	2024-02-09
Complete history	<a href="#">See info</a>



Registration #1	2015-09-30	13 mi
Registration #2	2018-09-26	27.532 mi
Registration #3	2019-09-26	44.397 mi
Registration #4	2019-09-26	44.397 mi
Registration #5	2020-08-31	61.469 mi
Registration #6	2020-08-31	61.469 mi
Registration #7	2020-08-31	61.469 mi
Registration #8	2020-08-31	61.469 mi
Registration #9	2020-08-31	61.469 mi
Registration #10	2020-08-31	61.469 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005688130 LN9