



report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SPORT
Colour	Silver
Year of manufacture	-
Top speed	142 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	249 Nm at 4.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	35.8 mpg
Consumption combined	27.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-28
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history****MOT #24** 2023-06-07 13:31**MOT test number** 798628465089**Result** ✓ Passed**Next expiry date** 2024-06-06**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Nearside Windscreen wiper blade defective wiper arm requires attention (3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #23** 2023-06-05 14:19**MOT test number** 132797915174**Result** ✗ Failed**Fail** Offside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**Minor** Nearside Windscreen wiper blade defective wiper arm requires attention (3.4 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #22** 2022-05-05 11:21**MOT test number** 747093505963**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Outer Suspension arm ball joint dust cover severely deteriorated Rose joint (5.3.4 (b) (i))**Advice** Both front wipers poor**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Rear Outer Suspension arm ball joint dust cover severely deteriorated Rose joint (5.3.4 (b) (i))

**MOT #21**

2022-05-05 07:37

MOT test number

425378545131

Result**✗ Failed****Minor**

Nearside Rear Outer Suspension arm ball joint dust cover severely deteriorated Rose joint (5.3.4 (b) (i))

Fail

Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill / inner arch (5.3.6 (a) (i))

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Minor

Offside Rear Outer Suspension arm ball joint dust cover severely deteriorated Rose joint (5.3.4 (b) (i))

Advice

Both front wipers poor

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20

2021-05-05 10:23

MOT test number

622723904216

Result**✓ Passed****MOT #19**

2021-05-05 08:11

MOT test number

918621707061

Result**✗ Failed****Fail**

Front Registration plate missing (0.1 (a))

**MOT #18**

2021-03-15 10:07

MOT test number

279796460491

Result**✗ Failed**

Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Rear Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Rear Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #17

2020-01-31 11:40

MOT test number

877158831172

Result**✓ Passed**

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16

2019-01-29 09:22

MOT test number

937491634347

Result**✓ Passed****MOT #15**

2018-02-23 16:00

MOT test number

913710940628

Result**✓ Passed****MOT #14**

2017-02-17 08:54

MOT test number

184951613491

Result**✓ Passed**

**MOT #13** 2016-02-17 13:45**MOT test number** 557041599885**Result** ✓ Passed**Advice** Slight corrosion to brake pipes**MOT #12** 2015-02-27 16:09**MOT test number** 728848955086**Result** ✓ Passed**Notice** Slight corrosion to brake pipes**Notice** Both rear tyres perished and split**MOT #11** 2015-02-18 13:42**MOT test number** 589809645060**Result** ✗ Failed**Notice** Slight corrosion to brake pipes**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)**Notice** Both rear tyres perished and split**MOT #10** 2014-02-14 12:19**MOT test number** 156455444084**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-02-18 12:51**MOT test number** 758759443066**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)



MOT #8	2012-02-10 11:30
---------------	------------------

MOT test number	445181742026
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2012-02-10 09:22
---------------	------------------

MOT test number	676701742073
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Registration plate character(s) incorrectly spaced (6.3.4a)
-------------	---

MOT #6	2011-02-03 10:12
---------------	------------------

MOT test number	938534931043
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2009-12-23 09:42
---------------	------------------

MOT test number	461507259395
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2008-12-01 15:58
---------------	------------------

MOT test number	793886438385
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--

MOT #3	2007-12-13 12:56
---------------	------------------

MOT test number	680497947372
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2006-12-16 10:52
---------------	------------------

MOT test number	914120556342
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2006-12-16 09:13
MOT test number	402680956437
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	YP53VFU
Plate since	2019-03-28
Current registration	YP53VFU
Plate since	2019-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	26
First mileage registration	2003-12-22
Last registration	2023-06-07
Complete history	See info



Registration #1	2003-12-22	29 mi
Registration #2	2006-12-16	33.249 mi
Registration #3	2006-12-16	33.257 mi
Registration #4	2007-12-13	43.106 mi
Registration #5	2008-12-01	54.108 mi
Registration #6	2009-12-23	59.336 mi
Registration #7	2011-02-03	62.399 mi
Registration #8	2012-02-10	65.101 mi
Registration #9	2012-02-10	65.101 mi
Registration #10	2013-02-18	67.495 mi
Registration #11	2014-02-14	70.175 mi
Registration #12	2015-02-18	71.728 mi
Registration #13	2015-02-27	71.728 mi
Registration #14	2016-03-01	75.377 mi
Registration #15	2016-03-01	75.377 mi
Registration #16	2016-03-01	75.377 mi
Registration #17	2016-03-01	75.377 mi
Registration #18	2016-03-01	75.377 mi
Registration #19	2016-03-01	75.377 mi
Registration #20	2016-03-01	75.377 mi
Registration #21	2016-03-01	75.377 mi
Registration #22	2016-03-01	75.377 mi
Registration #23	2016-03-01	75.377 mi
Registration #24	2016-03-01	75.377 mi
Registration #25	2016-03-01	75.377 mi
Registration #26	2016-03-01	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	303038376JB