



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	White
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 4

Date	2021-11-06
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 3

Date	2021-11-04
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-09-12
Pictures	13
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-10
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-09-26
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	21
Total items failed	10

MOT #14	2022-09-26 10:52
MOT test number	331448795787
Result	✓ Passed
Next expiry date	2023-09-26
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Nail in tyre

MOT #13	2021-09-27 14:34
MOT test number	852218753973
Result	✓ Passed

MOT #12	2021-09-22 12:13
MOT test number	433714348658
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #11	2021-02-09 15:34
MOT test number	299111010066
Result	✓ Passed
Advice	Lower under tray and top covers fitted

**MOT #10** 2020-01-30 15:56**MOT test number** 652121632563**Result** ✓ Passed**MOT #9** 2019-01-03 16:38**MOT test number** 528660310829**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2019-01-03 16:38**MOT test number** 760784059947**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #7** 2018-02-01 09:35**MOT test number** 626450768022**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2018-01-30 16:19**MOT test number** 668545916048**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside rear brake binding (3.7.B.1)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Nearside Front Steering system has a tyre fouling a part of the vehicle (2.2.D.2a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-01-09 16:54**MOT test number** 116113034514**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-06-23 13:29**MOT test number** 329444475130**Result** ✓ Passed

**MOT #3** 2015-06-22 08:42**MOT test number** 265813975176**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**MOT #2** 2014-06-26 12:02**MOT test number** 278087774448**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Slight leak from o/s/r coolant pipe**MOT #1** 2014-06-26 12:02**MOT test number** 796197974140**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Slight leak from o/s/r coolant pipe



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	VE11JKK
Plate since	2019-09-28
Current registration	VE11JKK
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-06-30
Last registration	2022-09-26
Complete history	See info



Registration #1	2011-06-30	20 mi
Registration #2	2014-06-26	65.201 mi
Registration #3	2015-06-22	115.686 mi
Registration #4	2015-06-23	115.686 mi
Registration #5	2017-01-09	121.209 mi
Registration #6	2018-01-30	123.281 mi
Registration #7	2018-02-01	123.281 mi
Registration #8	2019-01-03	130.565 mi
Registration #9	2019-01-03	130.565 mi
Registration #10	2019-01-03	130.565 mi
Registration #11	2019-01-03	130.565 mi
Registration #12	2019-01-03	130.565 mi
Registration #13	2019-01-03	130.565 mi
Registration #14	2019-01-03	130.565 mi
Registration #15	2019-01-03	130.565 mi
Registration #16	2019-01-03	130.565 mi
Registration #17	2019-01-03	130.565 mi
Registration #18	2019-01-03	130.565 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBB827791