






report date: 2024-03-28

General information

Make	ТОУОТА
Model	PRIUS VVT-I EXCEL
Colour	White
Year of manufacture	2017
Top speed	112 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	121 BHP
Max. torque	163 Nm at 3.600 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	91.1 mpg
Consumption extra urban	83.1 mpg
Consumption combined	85.6 mpg
CO2 emission	76 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-13

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

Advice

MOT expiry date	2024-10-09
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #7	023-09-18 09:39
MOT test number	245897968169
Result	✓ Passed
Next expiry date	2024-10-09
Advice Child Seat fitted not allowing full inspection of adult belt nearside rear and offside r	ear

MOT #6	2022-10-10 11:09	
MOT test number	716147783318	
Result	✓ Passed	
MOT #5	2022-04-25 20:02	
MOT test number	850803238856	
Result	✓ Passed	
MOT #4	2021-11-05 15:01	
MOT test number	715812046686	
Result	✓ Passed	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2021-11-04 16:00 501933335806 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Fail **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice**

MOT #2	2020-11-11 09:22
MOT test number	775180310091
Result	✓ Passed

NOT #1	2020 11 11 00:22
MOT #1	2020-11-11 09:22
MOT test number	290245369538
Result	★ Failed
Pass with rectification (b) (ii))	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4
(b) (ii))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	D
First licence fee (12 months)	£ 120,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	AK (NA)
Plate since	
	More info >

CarCheck.co.uk page 8/11



PN67XTZ report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



PN67XTZ report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-30
Last registration	2023-09-18
Complete history	See info



Registration #1	2017-09-30	23 mi
Registration #2	2020-11-11	11.669 mi
Registration #3	2020-11-11	11.669 mi
Registration #4	2021-11-04	19.460 mi
Registration #5	2021-11-05	19.460 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		0.777-44

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	82%
Pedestrian	77%
Safety systems	85%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1470 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1375 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	43 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number 2ZRS084105