





report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ASTRA SRI NAV CDTI S/S
Colour	Black
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

## Entry 2

Date 2021-07-02

Pictures 23

Listing price <u>View report</u>









source: cargurus.co.uk

### Entry 1

Date	2021-07-01
Pictures	25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



DP18UYB report date: 2024-03-28

MOT history

MOT expiry date	2024-11-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	6
Total items failed	2

MOT #5	2023-10-31 11:03
MOT test number	963234491865
Result	<b>✓</b> Passed
Next expiry date	2024-11-01

MOT #4		2022-11-02 11:38
MOT test	number	760837073544
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Track rod end ball joint has slight play and inner (2.1.3 (b) (i))	

MOT #3	2022-10-14 14:36
MOT test number	513071124402
Result	<b>×</b> Failed
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no long of dirt (6.1.7 (g) (ii))	er prevents the ingress
Advice Nearside Track rod end ball joint has slight play & inner (2.1.3 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3	(d) (ii))
Fail Offside Rear Bumper damaged and likely to cause injury when grazed or cont	acted (6.1.4 (a) (i))
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2	2021-09-07 09:03
MOT test number	470698379247
Result	<b>✓</b> Passed
MOT #1	2021-04-09 11:01
	000045000704
MOT test number	982345603721

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	1 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

Date

**Category** 

**Type** 



#### Extra VAUXHALL salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

**DP18UYB** 

report date: 2024-03-28

# For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report here.

# Plate changes

See in this check if this VAUXHALL had different number plates.

More info >

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-06-30
Last registration	2023-10-31
Complete history	See info



Registration #1	2018-06-30	17 mi
Registration #2	2021-04-09	73.654 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Safety ratings

NCAP rating	****	
Adult	86%	
Children	84%	
Pedestrian	83%	
Safety systems	75%	
Overall rating	83%	
Video	see crash video	



# Dimensions & weight

Width	2042 mm
Height	1510 mm
Length	4702 mm
Wheel base	2662 mm
Kerb weight	1318 kg
Max. allowed weight	1950 kg

# Additional information

Fuel tank capacity	48 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles	2	
Engine number	A2173198JCAX0325LVL	

CarCheck.co.uk page 11/11