



Mercedes-Benz

FX60YEE

report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 109 CDI LONG P/V
Colour	Silver
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2025-04-16
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	17
Total items failed	12

MOT #18	2024-03-18 10:29
MOT test number	399687540331
Result	✓ Passed
Next expiry date	2025-04-16

MOT #17	2023-04-17 16:16
MOT test number	913838014919
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2023-03-24 15:06
MOT test number	126005272458
Result	✗ Failed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2022-02-03 15:33**MOT test number** 256518007976**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #14** 2022-02-03 09:01**MOT test number** 393391438339**Result** ✗ Failed**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13** 2021-02-06 09:52**MOT test number** 970700971219**Result** ✓ Passed**MOT #12** 2021-02-06 09:52**MOT test number** 610821723136**Result** ✗ Failed**Pass with rectification** All direction indicators incorrect colour (4.4.3 (a))**Pass with rectification** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (ii))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11** 2020-01-15 11:48**MOT test number** 680294658974**Result** ✓ Passed**MOT #10** 2019-01-11 11:02**MOT test number** 493416002894**Result** ✓ Passed**MOT #9** 2018-01-11 01:13**MOT test number** 436396708817**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2018-01-10 10:12**MOT test number** 491248434982**Result** ✗ Failed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Trailer electrical socket insecure (1.9.3a)

**MOT #7** 2017-10-19 13:56**MOT test number** 925602501590**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Direction indicators slightly discoloured (1.4.A.2f)**MOT #6** 2016-10-19 11:35**MOT test number** 128122878869**Result** ✓ Passed**MOT #5** 2016-10-19 11:35**MOT test number** 742074951577**Result** ✗ Failed**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**MOT #4** 2015-10-08 16:32**MOT test number** 388335234423**Result** ✓ Passed**MOT #3** 2015-10-07 12:17**MOT test number** 825486157684**Result** ✗ Failed**Fail** Rear coil spring broken both (2.4.C.1a)**MOT #2** 2014-10-11 10:00**MOT test number** 608904784282**Result** ✓ Passed



MOT #1	2013-08-30 09:48
MOT test number	835392343284
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 FX60YEE
Plate since	2024-03-29
Current registration	 FX60YEE
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-01
Last registration	2024-03-18
Complete history	See info



Registration #1	2010-09-01	14 mi
Registration #2	2013-08-30	35.763 mi
Registration #3	2014-10-11	46.854 mi
Registration #4	2015-10-07	57.232 mi
Registration #5	2015-10-08	57.357 mi
Registration #6	2016-10-19	71.831 mi
Registration #7	2016-10-19	71.831 mi
Registration #8	2017-10-19	86.739 mi
Registration #9	2018-01-10	90.256 mi
Registration #10	2018-01-11	90.257 mi
Registration #11	2019-01-01	90.257 mi
Registration #12	2019-01-01	90.257 mi
Registration #13	2019-01-01	90.257 mi
Registration #14	2019-01-01	90.257 mi
Registration #15	2019-01-01	90.257 mi
Registration #16	2019-01-01	90.257 mi
Registration #17	2019-01-01	90.257 mi
Registration #18	2019-01-01	90.257 mi
Registration #19	2019-01-01	90.257 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	64698051797731