



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D3 R-DESIGN
Colour	Red
Year of manufacture	2014
Top speed	130 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C








Internet history

Entry 1

Date	2022-01-06
Pictures	42
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #9	2024-01-18 09:17
MOT test number	544160799568
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Engine covers & undertrays fitted
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))

MOT #8	2023-01-16 09:13
MOT test number	656537641265
Result	✓ Passed
Advice	Engine covers & undertrays fitted

**MOT #7** 2023-01-10 09:49**MOT test number** 656836941732**Result** ✗ Failed**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Engine covers & undertrays fitted**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #6** 2022-01-12 09:30**MOT test number** 792909963684**Result** ✓ Passed**MOT #5** 2021-03-26 16:11**MOT test number** 662374187741**Result** ✓ Passed**MOT #4** 2020-10-16 09:09**MOT test number** 873541169161**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both front brake discs corroded on inner faces (1.1.14 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge Both rear tyres worn on inner edges 235/40 18 95y (5.2.3 (e))**MOT #3** 2019-04-03 08:16**MOT test number** 880591254770**Result** ✓ Passed



MOT #2	2018-04-10 10:19
MOT test number	285036685249
Result	✓ Passed

MOT #1	2017-04-20 11:38
MOT test number	947967864361
Result	✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
17 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	17 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-04-26
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2014-04-26	7 mi
Registration #2	2017-04-20	36.723 mi
Registration #3	2018-04-10	48.392 mi
Registration #4	2019-04-03	57.417 mi
Registration #5	2020-10-16	73.873 mi
Registration #6	2021-03-26	77.136 mi
Registration #7	2022-05-20	78.277 mi
Registration #8	2023-05-20	78.277 mi
Registration #9	2023-05-20	78.277 mi
Registration #10	2023-05-20	78.277 mi
Registration #11	2024-01-18	78.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1445 mm
Length	4369 mm
Wheel base	2646 mm
Kerb weight	1501 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1428876