




report date: 2024-03-28

## General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	172 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.4 mpg
Consumption extra urban	34.0 mpg
Consumption combined	28.0 mpg
CO2 emission	276 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-08
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-24
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	46
Total items failed	16

MOT #23	2023-10-23 09:49
MOT test number	505832197536
Result	✓ Passed
Next expiry date	2024-10-24

MOT #22	2022-10-06 10:32
MOT test number	344266184774
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2022-10-06 10:32
MOT test number	515711060781
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #20** 2021-10-25 09:07**MOT test number** 349719767182**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #19** 2021-10-22 12:50**MOT test number** 599460711415**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #18** 2020-10-19 14:49**MOT test number** 846121944467**Result** ✓ Passed**MOT #17** 2020-10-14 12:46**MOT test number** 951380677105**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #16** 2019-10-07 14:07**MOT test number** 250440060205**Result** ✓ Passed**Advice** Nearside Rear Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #15** 2019-10-07 09:25**MOT test number** 635581569112**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Handbrake travel**MOT #14** 2018-10-15 11:22**MOT test number** 586440628911**Result** ✓ Passed**MOT #13** 2017-10-25 14:27**MOT test number** 845348804215**Result** ✓ Passed

**MOT #12**

2017-10-23 13:22

**MOT test number**

195894110356

**Result****✗ Failed****Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Oil leak engine o/s**MOT #11**

2016-08-31 16:03

**MOT test number**

529291088736

**Result****✓ Passed****Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #10**

2016-08-31 10:31

**MOT test number**

846197014271

**Result****✗ Failed****Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2015-09-16 09:36**MOT test number** 198122539774**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit tread on 2mm (4.1.E.1)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #8** 2015-09-16 09:36**MOT test number** 661026342989**Result** ✗ Failed

- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit tread on 2mm (4.1.E.1)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Pass with rectification** Hazard warning switch insecure (1.4.B.1d)

**MOT #7** 2014-09-09 16:55**MOT test number** 475472154276**Result** ✓ Passed**MOT #6** 2014-09-09 16:55**MOT test number** 417492154276**Result** ✗ Failed

- Pass with rectification** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #5** 2013-09-18 12:13**MOT test number** 597201263258**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear seats in luggage compartment absent at time of test
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Tow bar ball absent at time of test
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2013-09-17 15:39**MOT test number** 469790663295**Result** ✗ Failed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear seats in luggage compartment absent at time of test
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Notice** Tow bar ball absent at time of test
- Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)





MOT #3	2012-09-18 12:22
MOT test number	696392362242
Result	✓ Passed
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #2	2011-09-23 13:21
MOT test number	396946561481
Result	✓ Passed

MOT #1	2010-09-09 11:09
MOT test number	410202250284
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 December 2024

✓  
**MOT**

**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-09-27
Last registration	2023-10-23
Complete history	<a href="#">See info</a>



Registration #1	2007-09-27	10 mi
Registration #2	2010-09-09	20.820 mi
Registration #3	2011-09-23	28.114 mi
Registration #4	2012-09-18	34.634 mi
Registration #5	2013-09-17	43.170 mi
Registration #6	2013-09-18	43.170 mi
Registration #7	2014-09-09	52.352 mi
Registration #8	2015-09-16	60.892 mi
Registration #9	2015-09-16	60.892 mi
Registration #10	2016-08-31	69.161 mi
Registration #11	2016-08-31	69.161 mi
Registration #12	2017-10-23	73.659 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi
Registration #21	2019-05-29	75.277 mi
Registration #22	2019-05-29	75.277 mi
Registration #23	2019-05-29	75.277 mi
Registration #24	2019-05-29	75.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1783 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2229 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7



<b>Number of axles</b>	2
<b>Engine number</b>	883173