





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	285 Nm at 1.600 rpm
Engine capacity	2.400 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-12-18

Pictures 5

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-12-11

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-04-02
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	7
Total items failed	10

MOT #9	9	2024-04-18 10:35
MOT te	st number	843440730171
Result		X Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Offside Rear Leaf spring main leaf fractured (5.3.1 (b) (ii))	
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #8		2023-04-03 13:41
MOT test nu	mber	515976059108
Result		✓ Passed
Minor Of	fside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1 (b)
Advice F (c) (i))	ront passenger door pillar deteriorated but the door can still be readily o	pened and closed (6.2.3
Minor W	indscreen wiper blade defective (3.4 (b) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #7 2023-04-03 13:41 **MOT** test number 511839348875 Result × Failed Minor Windscreen wiper blade defective (3.4 (b) (i)) Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Front passenger door pillar deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

MOT #6 2021-09-21 15:35
MOT test number 166837777790
Result ✓ Passed

MOT #5

MOT test number

Fass with rectification

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4

MOT test number

Result

2020-09-14 07:43

732131718519

✓ Passed

MOT test number
767690141133

Result

Kesult

Rear Brake pad(s) contaminated hub oil seal leaking oil. (1.1.13 (b))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Rear Tyre has ply or cords damaged 185/75/16c (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



MOT #2 2019-09-19 12:01

MOT test number 248996946995

Result ✓ Passed

Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2018-09-21 07:22

MOT test number 107732420879

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/11



Tax & MOT check





Tax status Expired at 1 December 2021

Days left 880 days too late

MOT expiry date 2 April 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	AIR AIR
Plate since	
Current registration	UK ZIZ
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-12-31
Last registration	2024-04-18
Complete history	See info



2010-12-31	25 mi
2018-09-21	37.257 mi
2019-09-19	44.923 mi
2020-09-11	55.430 mi
2020-09-14	55.430 mi
2021-09-21	78.102 mi
	11.777 es
	2018-09-21 2019-09-19 2020-09-11 2020-09-14

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Dimensions & weight

Width	2360 mm
Height	2601 mm
Length	5680 mm
Kerb weight	2047 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	NOT KNOWN

CarCheck.co.uk page 11/11