





General information

Make	PEUGEOT
Model	307 S
Colour	Grey
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	Н





Internet history	
Entry 1	
Date	2021-12-30
Pictures	1
Listing price	View report
A This dealer has	



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-11
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	26
Total items failed	2

MOT #17	2023-01-12 13:43
MOT test number	968000849495
Result	✓ Passed
Next expiry date	2024-01-11
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #16	2023-01-11 11:53
MOT test number	748325199930
Result	🗙 Failed
DANGEROUS Anti-roll bar likely to become detached (5.3.3 (a) (ii))	
MAJOR Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2021-12-29 09:25
MOT test number	152242160292
Result	✓ Passed
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	





MOT #14		2021-11-22 16:51
MOT test	number	923244429627
Result		🗙 Failed
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice	Nearside Rear Nail in tyre	
MAJOR	Offside Front Headlamp insecure (4.1.1 (c))	
MAJOR	Offside Front Steering rack gaiter missing or no longer prevents the ingress	of dirt (2.1.3 (g) (ii))
MAJOR	Offside Front Suspension component pin or bush excessively worn top mour	nt (5.3.4 (a) (i))
MAJOR	Offside Front Tyre fouling a part of the vehicle inner arch liner (5.2.3 (f))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
MAJOR	Nearside Front Headlamp aim not tested (4.1.2 (b))	
MAJOR	Offside Front Headlamp aim too low (4.1.2 (a))	
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
MAJOR	Offside Front Body panel damaged and likely to cause injury wing $(6.2.1 (a)$	(i))

MOT #13	2020-11-06 15:48
MOT test number	734718199164
Result	✓ Passed
Advice Offside Front Inner plastic wing cover damaged	





MOT #12		2020-11-06 09:45
MOT test	number	441380753405
Result		🗙 Failed
DANGER the extent	ROUS Offside Front Inner Steering rack has excessive free play detected at that safe steering is affected (steering rack fitted) knuckle (2.3 (a) (ii))	the steering wheel to
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Offside Front Inner plastic wing cover damaged	
_		
MOT #11		2019-11-14 11:01
MOT #11 MOT test	number	2019-11-14 11:01 573374937891
	number	
MOT test	number Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	573374937891
MOT test Result		573374937891 Passed
MOT test Result Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	573374937891 <pre></pre>

MOT #10	2018-11-16 10:26
MOT test number	453644369873
Result	✓ Passed
MOT #9	2017-11-17 14:22

1101 #3	2017-11-17 14.22
MOT test number	252181660816
Result	✓ Passed

MOT #8	2016-11-23 12:30
MOT test number	883209005254
Result	✓ Passed





MOT #7	2015-11-26 12:57
MOT test number	465704254687
Result	✓ Passed
МОТ #6	2014-11-19 15:40
MOT test number	498093124369
Result	✓ Passed
MOT #5	2013-11-07 08:24
MOT test number	405191513339
Result	✓ Passed
MOT #4	2013-11-06 16:43

MOT #4	2013-11-00 10.43
MOT test number	469660513336
Result	🗙 Failed
Fail Front registration plate character(s) incorrectly spaced (6.3.4a)	
Fail Rear registration plate character(s) incorrectly spaced (6.3.4a)	

MOT #3	2012-11-14 17:47
MOT test number	819699312374
Result	✓ Passed

MOT #2	2011-11-11 10:19
MOT test number	387945811390
Result	✓ Passed

MOT #1	2010-11-19 13:20
MOT test number	781943720311
Result	✓ Passed



Tax & MOT check

√ Taxed	Х МОТ
Tax due: 1 January 2025	Expired: 11 January 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	11 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plat	es.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-30
Last registration	2023-01-12
Complete history	<u>See info</u>



Registration #1	2007-11-30	23 mi
Registration #2	2010-11-19	23.647 mi
Registration #3	2011-11-11	26.151 mi
Registration #4	2012-11-14	28.688 mi
Registration #5	2013-11-06	30.980 mi
Registration #6	2013-11-07	30.980 mi
Registration #7	2014-11-19	33.532 mi
Registration #8	2015-11-26	36.171 mi
Registration #9	2016-11-23	38.382 mi
Registration #10	2017-11-17	40.146 mi
Registration #11		11.777 mi
Registration #11 Registration #12		00.000 est
		01.000 est 01.000 est 01.000 est
Registration #12		01,000 est 01,000 est 01,000 est 01,000 est
Registration #12 Registration #13		01,000 440 01,000 440 01,000 440 01,000 440 01,000 440
Registration #12 Registration #13 Registration #14		01,000 46 01,000 46 01,000 46 01,000 46 01,000 46 01,000 46
Registration #12 Registration #13 Registration #14 Registration #15		01,000 46 01,000 46 01,000 46 01,000 46 01,000 46 01,000 46 01,000 46
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1275 kg
Max. allowed weight	1700 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	FX6N3093351