



report date: 2024-03-28

General information

Make	FIAT
Model	SEDICI 16V DYNAMIC
Colour	Green
Year of manufacture	2007
Top speed	106 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-08-02
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-23
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	49
Total items failed	10

MOT #20 2023-07-24 14:09

MOT test number 998083665208

Result ✓ Passed

Next expiry date 2024-07-23

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** General corrosion to underside of vehicle
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #19 2021-11-15 10:04

MOT test number 773485844899

Result ✓ Passed

- Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18 2021-11-15 10:04

MOT test number 586069810076

Result ✗ Failed

- Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #172020-12-15 14:58

MOT test number560740534608

Result

✓ Passed

- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #16**

2020-12-15 10:57

MOT test number

617604126975

Result**✗ Failed**

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front brake hose insecure possibility of chaffing
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front brake hose insecure on mounting
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15

2019-06-03 09:45

MOT test number

489778073887

Result**✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases center to rear join (6.1.2 (a))
- Advice** Various underside components have light corrosion
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Macpherson strut pin or bush worn but not resulting in excessive movement nearside and offside top mount bearings slightly rough (5.3.4 (a) (i))
- Advice** Offside rear valve stem deteriorated

**MOT #14**

2019-06-03 09:45

MOT test number

511851979477

Result**✗ Failed****Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Various underside components have light corrosion**Advice** Exhaust has a minor leak of exhaust gases center to rear join (6.1.2 (a))**Advice** Offside rear valve stem deteriorated**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Macpherson strut pin or bush worn but not resulting in excessive movement nearside and offside top mount bearings slightly rough (5.3.4 (a) (i))**MOT #13**

2018-06-21 15:35

MOT test number

147380994533

Result**✓ Passed****MOT #12**

2017-09-18 10:58

MOT test number

807967037580

Result**✓ Passed****Advice** Rear Fuel Pipe/s corroded Filler Neck**Advice** Clutch is worn.**Advice** Fuel pipe slightly damaged Corroded/ Insecure (7.2.2)**MOT #11**

2016-09-09 12:03

MOT test number

489273898376

Result**✓ Passed****Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #10** 2016-09-09 09:52**MOT test number** 292483164250**Result** ✗ Failed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #9** 2015-09-16 15:42**MOT test number** 948525720244**Result** ✓ Passed**MOT #8** 2015-09-16 09:20**MOT test number** 439255036960**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-09-25 10:32**MOT test number** 819888964276**Result** ✓ Passed**MOT #6** 2013-09-09 14:14**MOT test number** 385582353408**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2012-09-21 15:52**MOT test number** 858885462277**Result** ✓ Passed**MOT #4** 2012-09-20 14:38**MOT test number** 999044462294**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2012-09-14 11:46**MOT test number** 809358252204**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber mounting bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Fail** Offside Front Suspension arm rubber mounting bonding deteriorated resulting in excessive movement (2.4.G.2)**MOT #2** 2011-09-16 15:42**MOT test number** 549839051271**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2010-09-13 15:00**MOT test number** 733836450254**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	23 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-28
Last registration	2023-07-24
Complete history	See info



Registration #1	2007-09-28	20 mi
Registration #2	2010-09-13	21.510 mi
Registration #3	2011-09-16	29.644 mi
Registration #4	2012-09-14	37.877 mi
Registration #5	2012-09-20	38.016 mi
Registration #6	2012-09-21	38.016 mi
Registration #7	2013-09-09	45.368 mi
Registration #8	2014-09-25	52.711 mi
Registration #9	2015-09-16	59.810 mi
Registration #10	2015-09-16	59.810 mi
Registration #11	2016-09-09	66.918 mi
Registration #12	2016-09-09	66.918 mi
Registration #13	2016-09-09	66.918 mi
Registration #14	2016-09-09	66.918 mi
Registration #15	2016-09-09	66.918 mi
Registration #16	2016-09-09	66.918 mi
Registration #17	2016-09-09	66.918 mi
Registration #18	2016-09-09	66.918 mi
Registration #19	2016-09-09	66.918 mi
Registration #20	2016-09-09	66.918 mi
Registration #21	2016-09-09	66.918 mi
Registration #22	2016-09-09	66.918 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1755 mm
Height	1620 mm
Length	4115 mm
Wheel base	2500 mm
Kerb weight	1195 kg
Max. allowed weight	2870 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8003285