



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 DESIGN
Colour	Red
Year of manufacture	2005
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-22
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-19
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	39
Total items failed	12

MOT #21 2023-08-16 12:53

MOT test number 214616630117

Result ✓ Passed

Next expiry date 2024-08-19

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Door sill covers fitted, not allowing for full inspection

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner body sill (5.3.6 (a) (i))

Advice Nearside Rear wheel bolts possibly not compatible with wheel

MOT #20 2022-08-20 12:43

MOT test number 124437904222

Result ✓ Passed

MOT #19 2022-08-20 12:43

MOT test number 214894781611

Result ✗ Failed

Pass with rectification Nearside Front Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

Pass with rectification Offside Front Direction indicator not working (4.4.1 (a) (ii))

**MOT #18**

2021-08-06 16:38

MOT test number

758698503878

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge On limit (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Ballpoint clamp has extra long bolt fitted. No effect to car.

MOT #17

2021-08-06 12:58

MOT test number

453890265673

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Ballpoint clamp has extra long bolt fitted. No effect to car.
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge On limit (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2020-10-13 09:53

MOT test number

950211771399

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #15	2019-04-05 15:52
MOT test number	982076971474
Result	✓ Passed
Advice	Rear silencer corroded
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #14	2019-04-05 13:19
MOT test number	837274019450
Result	✗ Failed
Advice	Rear silencer corroded
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #13	2018-04-06 10:22
MOT test number	944433013591
Result	✓ Passed
Advice	Oil leak
Advice	Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #12	2017-03-29 11:55
MOT test number	450907362383
Result	✓ Passed
Advice	Nearside Front tyre outer side-wall splitting.
Advice	Both front tyres distorted/out of shape.
Advice	Offside Front tyre outer side-wall splitting.

**MOT #11** 2015-08-22 11:16**MOT test number** 502871842041**Result** ✓ Passed**MOT #10** 2015-05-30 15:41**MOT test number** 295640755423**Result** ✓ Passed**MOT #9** 2013-12-05 14:12**MOT test number** 465269633462**Result** ✓ Passed**Notice** All tyres perished**MOT #8** 2012-11-30 12:51**MOT test number** 759845232328**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-12-09 11:45**MOT test number** 856213441354**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #6	2010-11-29 09:19
MOT test number	402083830316
Result	✓ Passed
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #5	2010-11-29 09:19
MOT test number	733123030307
Result	✗ Failed
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
Pass with rectification	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Pass with rectification	Rear Registration plate lamp not working (1.1.C.1d)

MOT #4	2009-10-17 15:27
MOT test number	412520299266
Result	✓ Passed
Notice	Hand brake slightly stiff in operation
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #3	2009-10-17 15:27
MOT test number	833020199214
Result	✗ Failed
Pass with rectification	Registration plate lamp not working (1.1.5c)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Hand brake slightly stiff in operation
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #2	2008-09-25 10:34
MOT test number	371449068231
Result	✓ Passed

MOT #1	2008-09-25 10:34
MOT test number	994589568207
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
19 August 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	LB05DVR
Plate since	2019-03-29
Current registration	LB05DVR
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-05-31
Last registration	2023-08-16
Complete history	See info



Registration #1	2005-05-31	26 mi
Registration #2	2008-09-25	22.132 mi
Registration #3	2009-10-17	32.191 mi
Registration #4	2010-11-29	40.544 mi
Registration #5	2011-12-09	44.563 mi
Registration #6	2012-11-30	49.717 mi
Registration #7	2013-12-05	52.362 mi
Registration #8	2015-05-30	55.509 mi
Registration #9	2015-08-22	55.913 mi
Registration #10	2017-03-29	57.109 mi
Registration #11	2019-05-20	58.305 mi
Registration #12	2019-05-20	58.305 mi
Registration #13	2019-05-20	58.305 mi
Registration #14	2019-05-20	58.305 mi
Registration #15	2019-05-20	58.305 mi
Registration #16	2019-05-20	58.305 mi
Registration #17	2019-05-20	58.305 mi
Registration #18	2019-05-20	58.305 mi
Registration #19	2019-05-20	58.305 mi
Registration #20	2019-05-20	58.305 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	991 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST35283455