



General information

Make	FIAT
Model	500C SPORT
Colour	Black
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 3


Date	2021-08-07
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2


Date	2021-07-06
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-22
Pictures	16
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-04
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	23
Total items failed	15

MOT #15 2023-06-05 15:32**MOT test number** 667363546116**Result** Passed**Next expiry date** 2024-06-04**Minor** Front Headlamp lens slightly defective both worn (4.1.1 (b) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Front Macpherson strut corroded but not seriously weakened both (5.3.3 (b) (i))**MOT #14** 2022-03-12 13:13**MOT test number** 313106496791**Result** Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both tyres (5.2.3 (d) (ii))**Advice** Front Coil spring worn both coils (5.3.1 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Tyre slightly damaged/cracking or perishing both tyres (5.2.3 (d) (ii))**Advice** Rear Coil spring worn both coils (5.3.1 (b) (i))**MOT #13** 2021-04-23 11:26**MOT test number** 153273782471**Result** Passed



MOT #12	2021-04-22 09:11
MOT test number	699595523223
Result	✗ Failed
DANGEROUS Stop lamp(s) all not working (4.3.1 (a) (iii))	

MOT #11	2020-10-14 11:10
MOT test number	999210283933
Result	✗ Failed
MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS Offside Rear Suspension component pin or bush likely to become detached (5.3.4 (a) (ii))	
MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Oil leaking excessively from engine Sump (8.4.1 (a) (i))	
DANGEROUS Nearside Rear Suspension component pin or bush likely to become detached (5.3.4 (a) (ii))	

MOT #10	2019-04-11 12:51
MOT test number	303701276083
Result	✓ Passed
Advice Front tyres wearing thin	

MOT #9	2017-11-29 15:58
MOT test number	669692550363
Result	✓ Passed



MOT #8	2017-11-28 10:07
MOT test number	588058528618
Result	✗ Failed
Fail	Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
Fail	Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)
Fail	Rear brake application uneven (3.7.B.2)
Fail	Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Driver's door cannot be opened from outside the vehicle (6.2.B.1b)
Fail	Front brake application uneven (3.7.B.2)
Fail	Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)
Fail	Parking brake lever has no reserve travel (3.1.6b)

MOT #7	2016-09-08 12:17
MOT test number	563069656602
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2016-09-07 11:23**MOT test number** 533477900990**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)**Fail** Passenger door cannot be opened from outside the vehicle boot (6.2.B.1c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #5** 2015-09-03 13:55**MOT test number** 170032291908**Result** ✓ Passed**MOT #4** 2014-07-15 14:40**MOT test number** 739506994125**Result** ✓ Passed**MOT #3** 2014-07-14 15:54**MOT test number** 997205094104**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #2** 2013-07-31 13:08**MOT test number** 297202513283**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2013-07-31 11:33
MOT test number	767812613249
Result	✗ Failed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
4 June 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	4 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	KR10NJU
Plate since	2024-03-28
Current registration	KR10NJU
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-24
Last registration	2023-06-05
Complete history	See info



Registration #1	2010-06-24	22 mi
Registration #2	2013-07-31	30.115 mi
Registration #3	2013-07-31	30.115 mi
Registration #4	2014-07-14	33.578 mi
Registration #5	2014-07-15	33.580 mi
Registration #6	2015-09-03	36.427 mi
Registration #7	2016-09-07	56.810 mi
Registration #8	2016-09-08	56.810 mi
Registration #9	2017-11-28	76.950 mi
Registration #10	2017-11-29	76.950 mi
Registration #11	2018-06-20	76.950 mi
Registration #12	2018-06-20	76.950 mi
Registration #13	2018-06-20	76.950 mi
Registration #14	2018-06-20	76.950 mi
Registration #15	2018-06-20	76.950 mi
Registration #16	2018-06-20	76.950 mi
Registration #17	2018-06-20	76.950 mi
Registration #18	2018-06-20	76.950 mi
Registration #19	2018-06-20	76.950 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6058766