





report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Grey
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-07-09

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-05
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	48
Total items failed	3

MOT #13	2023-06-26 09:19
MOT test number	748420735945
Result	✓ Passed
Next expiry date	2024-07-05
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply (d) (i))	or cords Near tyre valve (5.2.3

MOT #12		2023-06-26 09:19
MOT test	number	864647565001
Result		★ Failed
Advice (d) (i))	Nearside Front T	yre has a cut but not deep enough to reach the ply or cords Near tyre valve (5.2.3
Pass wit	th rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #11	2022-07-06 10:17
MOT test number	503669362332
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



Passed

MOT #10 2022-07-06 10:17

MOT test number 665439619384

Result X Failed

Pass with rectification Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2

(c))

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2021-05-28 16:37

MOT test number 327807508389

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8 2020-05-28 12:50

MOT test number 407864294400

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

CarCheck.co.uk page 4/14



Advice

(i))

EN11LXI report date: 2024-03-28

MOT #7 2020-05-28 09:20

MOT test number 694695455614 Result × Failed **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Nearside Front Road wheel fixing missing bolt (5.2.1 (a) (i)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2019-06-08 09:14

MOT test number 106059870956

Result Passed **Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

CarCheck.co.uk page 5/14



(i))

EN11LXJ report date: 2024-03-28

MOT #5 2018-06-09 10:58 **MOT** test number 196095873815 Result Passed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

MOT #4 2017-06-03 08:48 **MOT** test number 653477153296 Result Passed **Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement **Advice** (2.4.G.2)

MOT #3	2016-05-28 10:26
MOT test number	208638312069
Result	✓ Passed

CarCheck.co.uk page 6/14

Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2) Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1) Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)	Nearside Front Suspension anni rubber bush deteriorated but not resulting in excessive movement
Advice (2.4.G.2)	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2 2015-05-30 11:56

MOT test number 249790055483

Result ✓ Passed

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

MOT #1 2014-06-14 11:42

MOT test number 906175064156

Result
✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK NA
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-27
Last registration	2023-06-26
Complete history	See info



Registration #1	2011-06-27	26 mi
Registration #2	2014-06-14	14.233 mi
Registration #3	2015-05-30	18.909 mi
Registration #4	2016-05-28	22.906 mi
Registration #5	2017-06-03	27.117 mi
Registration #6	2018-06-09	31.233 mi
Registration #7	2019-06-08	35.227 mi
Registration #8	2020-05-28	38.590 mi
Registration #9		11.777 mi
Registration #10		77,777 66
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		11.777 no

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1350 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 14/14

Engine number

FJBG1047469