






report date: 2024-03-28

## General information

Make	MERCEDES
Model	SL SL500
Colour	Blue
Year of manufacture	2002
Top speed	155 mph
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	315 BHP
Max. torque	470 Nm at 3.900 rpm
Engine capacity	4.966 cc
Cylinders	8
Fuel type	Petrol
CO2 emission	304 g/km
CO2 label	М



CarCheck.co.uk page 1/13



## Internet history

### Entry 1

Date 2021-08-29

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



# MOT history

MOT expiry date	2021-11-24
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	21
Total items failed	9

MOT #16		2020-11-25 12:04
MOT test	number	869026854091
Result		✓ Passed
Next expi	y date	2021-11-24
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15		2019-11-11 16:17
MOT test	number	224253119915
Result		✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	All tyres have cuts to outer	

CarCheck.co.uk page 3/13



**MOT #14** 2019-11-05 16:59

**MOT test number** 986642117916

Result X Failed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** All tyres have cuts to outer

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #13 2018-10-19 14:30

**MOT test number** 700791792040

**Result** 
✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2017-09-16 10:52

**MOT test number** 768258365709

**Result** 
✓ Passed

**MOT #11** 2017-09-16 10:52

MOT test number 406036181186

**Result** X Failed

Pass with rectification Supplementary Restraint System warning lamp indicates a fault (5.4.2)

CarCheck.co.uk page 4/13



Result

DF52BJX report date: 2024-03-28

Passed

**MOT #10** 2016-04-22 12:19

MOT test number 147712602794

**Result** ✓ Passed

Advice Nearside front, offside front and offside rear tyres cuts to tyre but no visable cords

MOT #9 2015-01-30 15:16

**MOT test number** 768400835045

**Notice** Engine covers fitted obscuring some components in the engine bay

**Notice** Under-trays fitted obscuring some underside components

**MOT #8** 2015-01-29 16:02

MOT test number 107069325485

Result X Failed

**Notice** Engine covers fitted obscuring some components in the engine bay

**Fail** Offside Inner Rear Tyre has ply or cords exposed (4.1.D.1b)

**Notice** Under-trays fitted obscuring some underside components

**Notice** Engine noisey

**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

MOT #7 2012-10-30 09:55

**MOT test number** 185804602301

**Result** ✓ Passed

Notice SRS lamp on

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the

ingress of dirt (2.4.G.2)

CarCheck.co.uk page 5/13



MOT #6 2011-07-01 13:14

**MOT test number** 166932681154

MOT #5 2011-06-30 12:21

**MOT test number** 605261781101

Result X Failed

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #4 2010-06-11 14:39

**MOT test number** 232812760139

**Notice** Nearside door mirror damaged.

MOT #3 2006-09-18 09:52

**MOT test number** 370151066261

**Result** ✓ Passed

MOT #2 2006-03-15 15:46

**MOT test number** 131364776077

**Result** ✓ Passed

MOT #1 2006-03-06 15:05

MOT test number 832155066024

**Result** X Failed

Fail Power steering component(s) leaking (2.3.3b)

CarCheck.co.uk page 6/13



# Tax & MOT check



X MOT

Tax expired: 9 July 2021

Expired: 24 November 2021

Tax status	Expired at 9 July 2021
Days left	1024 days too late
MOT expiry date	24 November 2021
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13




## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <a href="here">here</a> for the results.

### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



### Extra MERCEDES salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	m.o.o
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 10/13



## Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2002-11-11
Last registration	2020-11-25
Complete history	See info



Registration #1	2002-11-11	23 mi
Registration #2	2006-03-06	6.676 mi
Registration #3	2006-03-15	6.693 mi
Registration #4	2006-09-18	15.250 mi
Registration #5	2010-06-11	33.848 mi
Registration #6	2011-06-30	35.933 mi
Registration #7	2011-07-01	35.940 mi
Registration #8	2012-10-30	44.020 mi
Registration #9	2015-01-29	50.293 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 au

More info >

page 12/13 CarCheck.co.uk



# Additional information

Number of axles	2
Engine number	NK

CarCheck.co.uk page 13/13