



report date: 2024-03-28

General information

Make	MAZDA
Model	RX-8 RX-8 231PS
Colour	Grey
Year of manufacture	2006
Top speed	146 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	237 BHP
Max. torque	216 Nm at 6.000 rpm
Engine capacity	2.616 cc
Cylinders	2
Fuel type	Petrol
Consumption city	17.9 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.8 mpg
CO2 emission	284 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-14
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-12
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	27
Total items failed	13

MOT #21	2023-12-13 14:31
MOT test number	539008190504
Result	✓ Passed
Next expiry date	2024-12-12
Advice	Tyre slightly damaged/cracking or perishing All 4 (5.2.3 (d) (ii))

MOT #20	2023-12-12 08:46
MOT test number	674879077306
Result	✗ Failed
Advice	Tyre slightly damaged/cracking or perishing All 4 (5.2.3 (d) (ii))
Fail	Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

MOT #19	2022-05-10 09:34
MOT test number	428562768653
Result	✓ Passed

**MOT #18**

2021-07-22 08:54

MOT test number

521366032918

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread delaminated (0.1 (b))
- Advice** Front Exhaust catalyst heat shield corroded through where fitted as original equipment to unit, but no risk of fire at the time of test
- Advice** Front Brake pad(s) wearing thin Both sides of axle (1.1.13 (a) (ii))
- Advice** Nearside Rear Obvious water ingress to lamp(s) but this does not seriously affect function of unit at the time of test
- Advice** General corrosion to various underside components

MOT #17

2020-07-20 13:53

MOT test number

160682384572

Result

✓ Passed

- Advice** Nearside rear lamp unit has water ingress (recommend replacement)
- Advice** Rear Registration plate deteriorated but not likely to be misread faded (0.1 (b))
- Advice** Engine covers and under trays fitted

MOT #16

2020-07-20 13:53

MOT test number

143946774713

Result

✗ Failed

- Advice** Nearside rear lamp unit has water ingress (recommend replacement)
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Engine covers and under trays fitted
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread faded (0.1 (b))

**MOT #15** 2019-03-28 13:33**MOT test number** 225942275145**Result** ✓ Passed**MOT #14** 2019-03-23 10:41**MOT test number** 582948004772**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #13** 2018-01-19 15:34**MOT test number** 877936141925**Result** ✓ Passed**MOT #12** 2018-01-19 15:34**MOT test number** 444366792645**Result** ✗ Failed**Pass with rectification** Offside Front Tie bar/rod locating pin insecure (2.4.G.3a)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Rear Tie bar/rod locating pin insecure (2.4.G.3a)**MOT #11** 2017-01-18 16:10**MOT test number** 728650647461**Result** ✓ Passed

**MOT #10**

2017-01-18 11:14

MOT test number

575416778178

Result**✗ Failed****Fail** Nearside Rear Anti-roll bar linkage insecure Ball joint broken on linkage (2.4.G.1)**Fail** Offside Front Tyre has ply or cords exposed Sidewall cracked (4.1.D.1b)**Advice** Both front tyres heavily worn on inner edge**Fail** Nearside Front Tyre has ply or cords exposed Sidewall cracked (4.1.D.1b)**Advice** Both rear tyres cracking heavily in tread but cords not exposed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9**

2016-01-19 12:26

MOT test number

311015665853

Result**✓ Passed****Advice** Rear tyres perished and cracking**Advice** Strongly advise front tyres due to wear on inner edge and cracking in tread**MOT #8**

2014-12-08 10:55

MOT test number

267792844371

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both front tyres worn on inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres heavily perished and cracked

**MOT #7** 2014-01-06 11:37**MOT test number** 286266604024**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front tyres heavily worn on inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-12-04 10:57**MOT test number** 155369132346**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-08-24 11:26**MOT test number** 417416631227**Result** ✓ Passed**MOT #4** 2010-08-16 12:35**MOT test number** 301158420462**Result** ✓ Passed**MOT #3** 2010-08-16 12:35**MOT test number** 530538020219**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar linkage fractured (2.4.G.1)**MOT #2** 2009-08-21 17:26**MOT test number** 323913839427**Result** ✓ Passed



MOT #1	2009-08-21 14:06
MOT test number	730013439220
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage insecure (2.4.G.1)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-05-10
Last registration	2023-12-13
Complete history	See info



Registration #1	2006-05-10	14 mi
Registration #2	2009-08-21	10.398 mi
Registration #3	2009-08-21	10.398 mi
Registration #4	2010-08-16	13.385 mi
Registration #5	2011-08-24	14.722 mi
Registration #6	2012-12-04	17.062 mi
Registration #7	2014-01-06	17.964 mi
Registration #8	2014-12-08	19.512 mi
Registration #9	2016-01-19	21.039 mi
Registration #10	2017-01-18	22.290 mi
Registration #11	2017-01-18	22.290 mi
Registration #12	2018-01-18	22.290 mi
Registration #13	2018-01-18	22.290 mi
Registration #14	2018-01-18	22.290 mi
Registration #15	2018-01-18	22.290 mi
Registration #16	2018-01-18	22.290 mi
Registration #17	2018-01-18	22.290 mi
Registration #18	2018-01-18	22.290 mi
Registration #19	2018-01-18	22.290 mi
Registration #20	2018-01-18	22.290 mi
Registration #21	2018-01-18	22.290 mi
Registration #22	2018-01-18	22.290 mi

More info >



Dimensions & weight

Width	1770 mm
Height	1340 mm
Length	4425 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B 487479