





report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE PLUS
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-13

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-10-20
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #15	2023-10-13 13:52
MOT test number	140173080817
Result	✓ Passed
Next expiry date	2024-10-20
Minor Front Suspension arm ball joint dust cover severely deteriorated both n covers (5.3.4 (b) (i)) Advice Offside Rear Wheel bearing has slight play minor amount of play (5.1.3)	,

MOT #14		2022-10-14 14:50
MOT test	number	872488969391
Result		✓ Passed
Minor	Nearside Front Suspension component ball joint dust cover severely det	reriorated (5.3.4 (b) (i))

MOT #13	2022-10-14 14:50
MOT test number	707480168403
Result	▼ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor Nearside Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #12	2021-10-21 15:06
MOT test number	520480386833
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11

MOT test number

Result

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10

MOT test number

Result

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Nail in tyre

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #9
 2018-12-22 13:00

 MOT test number
 613256288883

 Result
 ✓ Passed

MOT #8

MOT test number

Result

Pass with rectification

Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #7

MOT test number

889064300323

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2017-09-18 11:32
MOT test number	837731427019
Result	✓ Passed
MOT #5	2016-09-26 09:22
MOT test number	829681680684
Result	✓ Passed
MOT #4	2015-10-03 11:14
MOT test number	949952243175
Result	✓ Passed
MOT #3	2014-08-27 11:41
MOT test number	415229434284
Result	
Nesale	✓ Passed
TC-Suit	✓ Passed
MOT #2	✓ Passed 2013-06-29 12:03
MOT #2	2013-06-29 12:03
MOT #2 MOT test number	2013-06-29 12:03 276510083491
MOT #2 MOT test number	2013-06-29 12:03 276510083491
MOT #2 MOT test number Result	2013-06-29 12:03 276510083491 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 20 October 2024

Tax status	Expired at 31 March 2024
Days left	29 days too late
MOT expiry date	20 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner hist	ory
------------	-----

For how long did the current and previous owner(s) have this FORD? How many owners d Check it in the premium report and see all owner registrations. Download the full report h	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-30
Last registration	2023-10-13
Complete history	See info



Registration #1	2009-06-30	18 mi
Registration #2	2012-06-22	20.274 mi
Registration #3	2013-06-29	27.614 mi
Registration #4	2014-08-27	36.090 mi
Registration #5	2015-10-03	43.743 mi
Registration #6	2016-09-26	49.051 mi
Registration #7	2017-09-18	53.661 mi
Registration #8	2018-09-14	59.042 mi
Registration #9	2018-12-22	60.052 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		9.777 es

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1922 mm
Height	1481 mm
Length	3958 mm
Wheel base	2489 mm
Kerb weight	966 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles2Engine number9J10615