



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 T8 TWIN ENGINE INSCRIPTION PRO AWD
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 60 mph	4.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	401 BHP
Max. torque	400 Nm at 2.200 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	134.5 mpg
CO2 emission	49 g/km
CO2 label	A








Internet history

Entry 9


Date	2021-12-31
Pictures	64
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 8

Date	2021-11-26
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 7

Date	2021-10-23
Pictures	0
Listing price	View report

source: [heyicar.co.uk](https://www.heyicar.co.uk)

Entry 6

Date	2021-10-23
Pictures	44
Listing price	View report



source: autotrader.co.uk


Entry 5

Date	2021-10-02
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 4

Date	2021-10-02
Pictures	44
Listing price	View report



source: autotrader.co.uk

Entry 3

Date	2021-08-13
Pictures	5
Listing price	View report



source: heycar.co.uk

Entry 2

Date	2021-07-22
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-22
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-05-15
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #5	2024-04-18 14:38
MOT test number	442250917011
Result	✓ Passed
Next expiry date	2025-05-15

MOT #4	2023-05-12 09:56
MOT test number	222618717011
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3	2022-05-07 10:44
MOT test number	901919412792
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))



MOT #2	2022-05-07 09:24
MOT test number	884459771425
Result	✗ Failed
Advice	Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #1	2021-05-10 12:15
MOT test number	334040663582
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
15 May 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	15 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2018-05-16
Last registration	2024-04-18
Complete history	See info



Registration #1	2018-05-16	12 mi
Registration #2	2021-05-10	23.171 mi
Registration #3	2022-05-10	25.277 mi
Registration #4	2023-05-10	25.277 mi
Registration #5	2023-05-10	25.277 mi
Registration #6	2023-05-10	25.277 mi
Registration #7	2023-05-10	25.277 mi
Registration #8	2023-05-10	25.277 mi
Registration #9	2023-05-10	25.277 mi
Registration #10	2023-05-10	25.277 mi
Registration #11	2023-05-10	25.277 mi
Registration #12	2023-05-10	25.277 mi
Registration #13	2023-05-10	25.277 mi
Registration #14	2023-05-10	25.277 mi
Registration #15	2023-05-10	25.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	2086 kg
Max. allowed weight	2660 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2418418