



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI QUICKSHIFT
Colour	Blue
Year of manufacture	2010
Top speed	96 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	40.9 mpg
Consumption combined	38.1 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-15
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-08-25
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	16
Total items failed	9

MOT #16	2023-08-22 08:59
MOT test number	440927912309
Result	✓ Passed
Next expiry date	2024-08-25

MOT #15	2022-08-19 08:01
MOT test number	858553831756
Result	✓ Passed

MOT #14	2021-08-26 09:12
MOT test number	784046741661
Result	✓ Passed

MOT #13	2021-08-18 11:02
MOT test number	270657456358
Result	✗ Failed
<p><b>MAJOR</b> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</p> <p><b>MAJOR</b> Nearside Rear Brake pipe excessively corroded (1.1.11 (c))</p> <p><b>MAJOR</b> Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</p> <p><b>MAJOR</b> Offside Rear Brake pipe excessively corroded (1.1.11 (c))</p>	

**MOT #12** 2020-10-05 10:28**MOT test number** 172946464393**Result** ✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material Both Sides over trailing beam to chassis rusty / corroded (1.1.11 (c))

**Advice** Wheel Trims Fitted Unable to See Brake Pads and Discs

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #11** 2019-10-14 09:36**MOT test number** 461982852511**Result** ✓ Passed

**Advice** Rear Brake pipe corroded, covered in grease or other material Both Sides over trailing beam to chassis rusty / corroded (1.1.11 (c))

**Advice** Rear Seats and Wheel Chair Belts all checked. Winch Belt Checked All OK

**Advice** Wheel Trims Fitted Unable to See Brake Pads and Discs

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Rear Wheel Chair Ramp Checked and Secure. Stows Ok and Locks In.

**MOT #10** 2018-10-25 13:57**MOT test number** 477487810626**Result** ✓ Passed**MOT #9** 2018-10-25 10:02**MOT test number** 162831756081**Result** ✗ Failed

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #8** 2018-03-14 14:45**MOT test number** 154400278373**Result** ✓ Passed

**MOT #7** 2017-04-27 10:36**MOT test number** 618449303602**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #6** 2016-06-16 15:29**MOT test number** 337208067257**Result** ✓ Passed**MOT #5** 2016-06-14 12:51**MOT test number** 436543811612**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-08-10 10:46**MOT test number** 978282725280**Result** ✓ Passed**MOT #3** 2014-09-09 16:11**MOT test number** 767682454274**Result** ✓ Passed



MOT #2 2014-09-04 12:32

MOT test number 569207544295

Result ✗ Failed

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Notice** Offside wiper blade split

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)

**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #1 2013-10-23 16:14

MOT test number 365746293403

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
25 August 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	25 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YX60EZO
Plate since	2019-03-29
Current registration	YX60EZO
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-12-14
Last registration	2023-08-22
Complete history	<a href="#">See info</a>



Registration #1	2010-12-14	9 mi
Registration #2	2013-10-23	20.057 mi
Registration #3	2014-09-04	26.094 mi
Registration #4	2014-09-09	26.096 mi
Registration #5	2015-08-10	33.862 mi
Registration #6	2016-06-14	42.366 mi
Registration #7	2016-06-16	42.368 mi
Registration #8	2017-04-27	51.129 mi
Registration #9	2018-03-14	58.243 mi
Registration #10	2019-03-20	65.357 mi
Registration #11	2019-03-20	65.357 mi
Registration #12	2019-03-20	65.357 mi
Registration #13	2019-03-20	65.357 mi
Registration #14	2019-03-20	65.357 mi
Registration #15	2019-03-20	65.357 mi
Registration #16	2019-03-20	65.357 mi
Registration #17	2019-03-20	65.357 mi
Registration #18	2019-03-20	65.357 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1957 mm
Length	4782 mm
Kerb weight	1918 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	C102787