





report date: 2024-03-28

## General information

Make	KIA
Model	PICANTO GT-LINE S
Colour	White
Year of manufacture	2018
Top speed	112 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	99 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	48.7 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

## Entry 1

Date 2021-08-04

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



FL68NFX report date: 2024-03-28

B 4	$\sim$ $-$			
10.71	$\alpha$	- h	sto	rv
101	( ) I		510	II V
	•			. ,

MOT expiry date	2025-04-25
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	4

MOT #6	2024-04-26 15:55
MOT test number	305908449372
Result	✓ Passed
Next expiry date	2025-04-25

MOT #5		2023-11-30 12:48
<b>MOT</b> test	number	659339756122
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4	2023-11-30 11:12
MOT test number	693114740739
Result	<b>X</b> Failed
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2022-10-19 15:46
MOT test number 365925755771

Result \( \sqrt{Passed} \)

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Tyre slightly damaged/cracking or perishing both rear tyres cracking within the treads (5.2.3 (d)

MOT #2

2022-10-19 10:24

**MOT test number** 614763817070

Result X Failed

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall 195/45/16 (5.2.3 (d) (i))

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall 195/45/16 (5.2.3 (d) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Tyre slightly damaged/cracking or perishing both rear tyres cracking within the treads (5.2.3 (d)

(ii))

MOT #1 2021-08-02 15:52

MOT test number 212518643035

**Result** 
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check

Tax expired: 17 April 2024





Tax status	Expired at 17 April 2024
Days left	12 days too late
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Expires: 25 April 2025

## Tax calculation

48
G
£ 210,00,-
£ 180,00,-
£ 99,00,-
£ 570,00,-
£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
**********	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this KIA had different number plates.	
Number of plates	
Current registration	NK NY
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



FL68NFX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-11-20
Last registration	2024-04-26
Complete history	See info



Registration #1	2018-11-20	22 mi
Registration #2	2021-08-02	13.572 mi
Registration #3		11.777 es
Registration #4	2022-10-19	21.349 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



FL68NFX report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	64%
Pedestrian	54%
Safety systems	47%
Overall rating	68%
Video	see crash video



# Dimensions & weight

Width	1595 mm
Height	1485 mm
Length	3595 mm
Wheel base	2400 mm
Kerb weight	1020 kg
Max. allowed weight	1405 kg

# Additional information

Fuel tank capacity	35 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

**Engine number** G3LCJP096656