





report date: 2024-03-28

General information

Make	FORD
Model	FIESTA ST-LINE
Colour	Silver
Year of manufacture	2018
Top speed	125 mph
0 - 100 km/h	9.9 seconds
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 138 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	98 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-30

Pictures 2

Listing price <u>View report</u>





source: autoonline.co.uk

CarCheck.co.uk page 2/12



GV67ATO report date: 2024-03-28

MOT	history
-----	---------

MOT expiry date	2025-03-05
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	19
Total items failed	0

MOT #5		2024-03-06 16:11
MOT test	number	211668590413
Result		✓ Passed
Next expir	y date	2025-03-05
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Front Tyre slightly damaged/cracking or perishing 205/45/17 (5.2.3 (d) (ii))		
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #4 2024-03-05 12:12

MOT test number 313695320439

Result X Failed

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 205/45/17 (5.2.3 (d) (ii))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure 205/45/17 (5.2.3 (d) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice TPMS light on

Advice Offside Front Tyre slightly damaged/cracking or perishing 205/45/17 (5.2.3 (d) (ii))

MOT #3 2021-07-24 15:04

MOT test number 424962628014

Result \(\sqrt{Passed} \)

MOT #2 2021-01-29 11:44

MOT test number 115107651522

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2021-01-28 15:24

MOT test number 246315392827

Result X Failed

DANGEROUS Stop lamp(s) remains on when the brakes are released all stop lights (4.3.2 (a) (iii))

DANGEROUS Offside Front Brake hose damaged and likely to fail (1.1.12 (a))

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check

Tax expired: 18 April 2024





Expires: 5 March 2025

Tax status	Expired at 18 April 2024
Days left	10 days too late
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

48
Е
£ 165,00,-
£ 180,00,-
£ 99,00,-
£ 570,00,-
£ 313,50,-

CarCheck.co.uk page 6/12




GV67ATO report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



GV67ATO report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



GV67ATO report date: 2024-03-28

Owner history

e mier metery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



GV67ATO report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-01-29
Last registration	2024-03-06
Complete history	See info



Registration #1	2018-01-29	8 mi
Registration #2	2021-01-28	21.506 mi
Registration #3	2021-01-29	21.506 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 11/12



GV67ATO report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	64%
Safety systems	60%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1941 mm
Height	1476 mm
Length	4040 mm
Wheel base	2493 mm
Kerb weight	1064 kg

Additional information

Fuel tank capacity	42
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	JS33927 page 12/12