



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	HILUX HL2 4X4 D-4D ECB
Colour	Black
Year of manufacture	2010
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	142 BHP
Max. torque	343 Nm at 2.800 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	39.2 mpg
Consumption combined	34.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-16
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-11-21
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	16
Total items failed	9

MOT #15 2022-11-22 13:51

MOT test number 761562276655

Result ✓ Passed

Next expiry date 2023-11-21

Minor Offside Front Upper Macpherson strut ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Lower Macpherson strut ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2021-11-06 09:39

MOT test number 493528145351

Result ✓ Passed

MOT #13 2020-12-04 15:59

MOT test number 412224950915

Result ✓ Passed

**MOT #12** 2020-12-04 15:30**MOT test number** 649497982707**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11** 2019-12-18 09:49**MOT test number** 608131216635**Result** ✓ Passed**MOT #10** 2019-03-01 16:38**MOT test number** 897807128820**Result** ✓ Passed**MOT #9** 2019-02-28 11:03**MOT test number** 446099836670**Result** ✗ Failed**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Fail** Horn not working (7.7 (a) (ii))**MOT #8** 2018-02-27 12:33**MOT test number** 316356590697**Result** ✓ Passed**Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #7** 2018-02-23 09:16**MOT test number** 798635354282**Result** ✗ Failed**Advice** Offside Rear rear brake fluctuating, but not excessively (3.7.B.3)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Brake pipe slightly corroded all at load valve (3.6.B.2c)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Trailer electrical socket insecure (1.9.3a)**MOT #6** 2017-02-17 11:21**MOT test number** 764337722517**Result** ✓ Passed**Advice** Brake pipe slightly corroded brake pipes feeding rear limiter valve corroded (3.6.B.2c)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Brake pipe slightly corroded brake pipe feeding rear hose corroded (3.6.B.2c)**MOT #5** 2016-02-26 10:43**MOT test number** 250885677312**Result** ✓ Passed**MOT #4** 2016-02-24 09:09**MOT test number** 843405691888**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

**MOT #3** 2015-02-10 13:06**MOT test number** 146241345479**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2015-02-10 08:58**MOT test number** 126441145444**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2014-02-24 12:01**MOT test number** 115755754073**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-10
Last registration	2022-11-22
Complete history	See info



Registration #1	2010-12-10	20 mi
Registration #2	2014-02-24	39.095 mi
Registration #3	2015-02-10	47.767 mi
Registration #4	2015-02-10	47.767 mi
Registration #5	2016-02-24	58.255 mi
Registration #6	2016-02-26	58.255 mi
Registration #7	2017-02-17	67.200 mi
Registration #8	2018-02-23	76.850 mi
Registration #9	2018-02-27	76.938 mi
Registration #10	2019-05-29	85.377 mi
Registration #11	2019-05-29	85.377 mi
Registration #12	2019-05-29	85.377 mi
Registration #13	2019-05-29	85.377 mi
Registration #14	2019-05-29	85.377 mi
Registration #15	2019-05-29	85.377 mi
Registration #16	2019-05-29	85.377 mi
Registration #17	2019-05-29	85.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1810 mm
Length	5130 mm
Kerb weight	1890 kg
Max. allowed weight	3020 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	2KD7940831