



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER HDI S L1 850
Colour	White
Year of manufacture	2011
Top speed	100 mph
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN

**MOT history**

MOT expiry date	2024-10-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	13
Total items failed	5

MOT #12	2023-10-13 15:55
MOT test number	163967600170
Result	✓ Passed
Next expiry date	2024-10-12
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #11	2023-10-07 11:11
MOT test number	814699037661
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #10	2022-10-11 16:00
MOT test number	535806995738
Result	✓ Passed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #9** 2022-10-04 09:51**MOT test number** 341174889326**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Horn not working (7.7 (a))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #8** 2021-09-28 14:23**MOT test number** 227168969787**Result** ✓ Passed**MOT #7** 2019-06-20 16:18**MOT test number** 239119353156**Result** ✓ Passed**MOT #6** 2019-06-20 16:18**MOT test number** 222308758586**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #5** 2018-06-15 09:21**MOT test number** 599081979391**Result** ✓ Passed**Advice** FRONT DISCS WORN +FRONT SHOCKS WEAK

**MOT #4** 2017-06-15 09:43**MOT test number** 493905380429**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2016-06-21 16:31**MOT test number** 582602591808**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2015-09-14 17:31**MOT test number** 140841641625**Result** ✓ Passed**MOT #1** 2014-10-21 14:34**MOT test number** 928134394203**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Notice** O/s drive shaft oil seal leaking



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
12 October 2024

Tax status

Valid until 1 September

Days left

125

MOT expiry date

12 October 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-11-01
Last registration	2023-10-13
Complete history	See info



Registration #1	2011-11-01	9 mi
Registration #2	2014-10-21	66.945 mi
Registration #3	2015-09-14	86.400 mi
Registration #4	2016-06-21	97.424 mi
Registration #5	2017-06-15	109.199 mi
Registration #6	2018-06-15	118.291 mi
Registration #7	2019-06-20	130.173 mi
Registration #8	2020-06-20	141.217 mi
Registration #9	2021-06-20	151.217 mi
Registration #10	2022-06-20	161.217 mi
Registration #11	2023-06-20	171.217 mi
Registration #12	2024-06-20	181.217 mi
Registration #13	2025-06-20	191.217 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1336 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	JBCB0234269