



report date: 2024-03-29

General information

Make	NISSAN
Model	CABSTAR 35.14 SHR C/C TIPPER
Colour	White
Year of manufacture	2012
Top speed	85 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	270 Nm at 1.600 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	34.9 mpg
Consumption combined	31.4 mpg
CO2 emission	249 g/km
CO2 label	L





Internet history

Entry 1	
Date	2022-04-08
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-04
MOT pass rate	50 %
MOT passed	8
Failed MOT tests	8
Total advice items	59
Total items failed	41

MOT #16	2023-06-05 17:01
MOT test number	816638594499
Result	✓ Passed
Next expiry date	2024-06-04
Advice	Offside Rear Inner flat
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15	2023-05-31 14:01
MOT test number	231069647721
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Inner flat
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MOT #14	2022-05-18 15:21
MOT test number	330116669478
Result	✓ Passed

**MOT #13**

2022-05-18 15:21

MOT test number

152643560985

Result**✗ Failed****Pass with rectification**

Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Pass with rectification

Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Pass with rectification

Horn not working (7.7 (a))

MOT #12

2020-12-18 15:31

MOT test number

409282250398

Result**✓ Passed****Advice**

Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice

Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #11**

2020-11-23 16:36

MOT test number

406146570782

Result**✗ Failed****Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Side repeater likely to become detached (4.4.1 (c) (ii))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Side repeater missing (4.4.1 (a) (ii))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Horn not working (7.7 (a) (ii))**Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #10**

2019-10-02 14:23

MOT test number

140695511653

Result

✓ Passed

Advice Rear Service brake fluctuating, but not excessively both nearside and offside rear (1.2.1 (e))**Advice** Front both nearside and offside front wheel bearing slight play and visually unable to see if taper roller type fitted**Advice** Unable to perform servo or brake fluid level check during test unable to access**Advice** Parking brake 10 notches but still has reserve travel during operation and during test**MOT #9**

2019-10-02 10:32

MOT test number

622710031682

Result

✗ Failed

Advice Front both nearside and offside front wheel bearing slight play and visually unable to see if taper roller type fitted**Fail** Nearside Rear Suspension component pin or bush excessively worn anti roll bar d bush (5.3.4 (a) (i))**Fail** Offside Rear Lower Valve stem seriously damaged at wheel rim (5.2.3 (j))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment but still has reserve travel (1.1.6 (c))**Advice** Unable to perform servo or brake fluid level check during test unable to access**Fail** Offside Rear Suspension component pin or bush excessively worn anti roll bar d bush (5.3.4 (a) (i))**Advice** Rear Service brake fluctuating, but not excessively both nearside and offside rear (1.2.1 (e))

**MOT #8** 2019-09-12 11:48**MOT test number** 768953593380**Result** ✗ Failed**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Advice** Offside Rear Fluid leak, but not excessive outer hub area (8.4.1 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn lift in ball joint (5.3.4 (a) (i))**Fail** Offside Front Driver's seat insecure (6.2.5 (a) (ii))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced floor area (7.1.1 (a) (i))**Fail** Nearside Rear Fluid leak harmful to the environment or a risk to other road users hub seal (8.4.1 (a) (i))**Fail** Nearside Rear Brake disc contaminated (1.1.14 (b))**Advice** Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Offside Front Lower Suspension arm ball joint excessively worn lift in ball joint (5.3.4 (a) (i))**Fail** Offside Front Road wheel more than one fixing missing wheel nut missing (5.2.1 (a) (ii))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2018-06-29 07:55**MOT test number** 165026936198**Result** ✓ Passed**Advice** Nearside Front tyre wearing on edges**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Rear Inner Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**MOT #6**

2017-06-23 08:19

MOT test number

945840423245

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #5

2017-06-22 12:47

MOT test number

991882096589

Result

✗ Failed

- Fail** Nearside Side repeater not working (1.4.A.2c)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Offside Front Lower Shock absorber has an excessively worn bush (2.7.4)
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)



MOT #4

2016-06-21 15:43

MOT test number

235560905919

Result

✓ Passed

- Advice

Offside Front wheel bearing has slight play (2.5.A.3c)
- Advice

Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice

Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Front wheel bearing has slight play (2.5.A.3c)
- Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice

Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Rear Outer Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #3**

2016-06-15 13:05

MOT test number

164154872367

Result**✗ Failed**

- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Offside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)
- Advice** Offside Rear Outer Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Lower Shock absorber has an excessively worn bush (2.7.4)

MOT #2

2015-06-24 16:05

MOT test number

668415675138

Result**✓ Passed**



MOT #1	2015-06-22 17:04
MOT test number	387543975108
Result	✗ Failed
Fail	Rear Stop lamp emits other than a steady red light (1.2.1e)
Advice	Offside Rear Stop lamp deteriorated, but still visible from a reasonable distance (1.2.1d)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 June 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	4 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-07-30
Last registration	2023-06-05
Complete history	See info



Registration #1	2012-07-30	23 mi
Registration #2	2015-06-22	19.886 mi
Registration #3	2015-06-24	19.886 mi
Registration #4	2016-06-15	27.790 mi
Registration #5	2016-06-21	27.790 mi
Registration #6	2017-06-22	33.977 mi
Registration #7	2017-06-23	33.977 mi
Registration #8	2018-06-29	36.236 mi
Registration #9	2019-09-12	41.138 mi
Registration #10	2019-09-12	41.138 mi
Registration #11	2019-09-12	41.138 mi
Registration #12	2019-09-12	41.138 mi
Registration #13	2019-09-12	41.138 mi
Registration #14	2019-09-12	41.138 mi
Registration #15	2019-09-12	41.138 mi
Registration #16	2019-09-12	41.138 mi
Registration #17	2019-09-12	41.138 mi
Registration #18	2019-09-12	41.138 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2265 mm
Height	2122 mm
Length	4899 mm
Wheel base	2500 mm
Kerb weight	2271 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	78546B