



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI SE
Colour	White
Year of manufacture	2017
Top speed	104 mph
0 - 60 mph	17.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	343 Nm at 1.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	197 g/km
CO2 label	J





Internet history

Entry 2

Date	2022-03-27
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2022-01-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-06-12
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #6	2023-05-30 08:05
MOT test number	836035300259
Result	✓ Passed
Next expiry date	2024-06-12

MOT #5	2022-06-13 11:03
MOT test number	465206484784
Result	✓ Passed

MOT #4	2021-12-15 14:45
MOT test number	554047583083
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3.31mm to 0.00mm on inside edge (5.2.3 (e))
- Advice** Nearside Non obligatory mirror damaged Taped into position - recommend replacement or suitable repair - vision impaired
- Advice** Parking brake lever has little reserve travel
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.68mm to 0.00mm on outside edge (5.2.3 (e))

**MOT #3**

2021-12-15 13:17

**MOT test number**

242188149591

**Result****✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Non obligatory mirror damaged Taped into position - recommend replacement or suitable repair - vision impaired
- Advice** Parking brake lever has little reserve travel
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3.31mm to 0.00mm on inside edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Tyre pressure monitoring system light illuminated
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.68mm to 0.00mm on outside edge (5.2.3 (e))

**MOT #2**

2020-10-21 09:55

**MOT test number**

672357762713

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 5.63mm to 1.00mm on outside edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Non obligatory mirror damaged



MOT #1 2020-10-21 09:55

MOT test number 480119436008

Result ✗ Failed

**Advice** Nearside Non obligatory mirror damaged

**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 5.63mm to 1.00mm on outside edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
12 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	12 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>First licence fee (12 months)</b>	£ 1.565,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 2.220,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-01
Last registration	2023-05-30
Complete history	<a href="#">See info</a>



Registration #1	2017-09-01	12 mi
Registration #2	2020-10-21	19.963 mi
Registration #3	2020-10-21	19.963 mi
Registration #4	2021-12-15	26.706 mi
Registration #5	2021-12-15	26.706 mi
Registration #6	2022-05-20	26.706 mi
Registration #7	2022-05-20	26.706 mi
Registration #8	2022-05-20	26.706 mi
Registration #9	2023-05-30	26.706 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5150 mm
Wheel base	3200 mm
Kerb weight	2238 kg
Max. allowed weight	3070 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

<b>Number of axles</b>	2
<b>Engine number</b>	D4CBG164710