





report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 HDI SW SE
Colour	Silver
Year of manufacture	2005
Top speed	126 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2022-01-03

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2025-01-29
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	39
Total items failed	5

MOT #19		2024-01-30 17:27
MOT test	number	651340270686
Result		✓ Passed
Next expi	ry date	2025-01-29
Advice	Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Advice	Tyre worn close to legal limit/worn on edge all (5.2.3 (e))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #18 2024-01-09 15:05 **MOT** test number 636752270028 Result **X** Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Fail **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Front Play in steering rack inner joint(s) Both sides Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Fail Offside Rear Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i)) Fail Electronic stability control warning lamp indicates a fault (7.12 (e)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #17	2023-01-05 13:04
MOT test number	348689582205
Result	✓ Passed
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	

MOT #16	2022-01-08 15:54
MOT test number	260877849324
Result	✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #15	2021-09-01 11:26
MOT test	number 938504177396
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both rear tyres slightly on inner edges (5.2.3 (e))
Advice	Rear Coil spring corroded both side slightly in places (5.3.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Brake fluid is dark in colour - recommend to be replaced
Advice	Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

MOT #14		2020-09-01 09:34
MOT test	number	782699196913
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both fronts inner edges (5.2.3 (e))
Advice	Emissions was too clean to provide emissions printout	
Advice	Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Brake fluid is dark in colour - recommend to be replaced	

MOT #13	2019-08-14 09:54
MOT test number	525970527594
Result	✓ Passed
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #12	2018-08-20 14:34
MOT test number	655724028407
Result	✓ Passed

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT test number

Result

Advice
Both front wiper blades are smeary

Advice
Offside Front brake disc worn, pitted or scored, but not seriously weakened On inside (3.5.1i)

Advice
Front brake application is slightly uneven

Advice
Parking brake lever has little reserve travel (3.1.6b)

MOT #10 2016-08-22 08:29 **MOT** test number 920881148519 Result ✓ Passed 2015-08-21 14:14 **MOT** #9 **MOT** test number 757742316749 Result ✓ Passed **Advice** Slight play in o/s/f steering arm **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Rear tyre uneven wear

MOT test number

Result

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Oil leak

CarCheck.co.uk page 6/15



Result

WK55VMZ

report date: 2024-03-28

× Failed

MOT #7 2013-08-20 10:47

MOT test number 248562333251

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Brake pad(s) wearing thin (3.5.1g)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2012-08-22 11:00

MOT test number 197255932232

Result \rightarrow Passed

MOT #5 2011-08-16 15:18

MOT test number 387628021283

Result ✓ Passed

MOT #4 2010-09-06 15:45

MOT test number 590319040243

Result

Passed

MOT #3 2010-09-06 14:57

MOT test number 260719540204

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #2		2009-09-01 09:35
MOT test	number	222214549203
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Wiperblades slight smearing	
Notice	Slight oil leak from engine	

MOT #1	2008-09-02 14:08
MOT test number	481956148253
Result	✓ Passed

CarCheck.co.uk page 8/15





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates faste since

CarCheck.co.uk page 12/15



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-01
Last registration	2024-01-30
Complete history	See info



Registration #1	2005-09-01	8 mi
Registration #2	2008-09-02	28.351 mi
Registration #3	2009-09-01	34.263 mi
Registration #4	2010-09-06	40.677 mi
Registration #5	2010-09-06	40.677 mi
Registration #6	2011-08-16	45.631 mi
Registration #7	2012-08-22	50.690 mi
Registration #8	2013-08-20	56.595 mi
Registration #9	2014-08-11	61.037 mi
Registration #10	2015-08-21	66.349 mi
Registration #11	2016-08-22	70.963 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		11.777 mi

More info >

CarCheck.co.uk page 14/15



Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1471 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1623 kg
Max. allowed weight	2195 kg

Additional information

· · · · · · · · · · · · · · · · · · ·		
Fuel tank capacity	66 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 15/15

Engine number

DYTE4104873