





report date: 2024-03-29

General information

Make	MAZDA
Model	CX-5 SPORT NAV
Colour	Grey
Year of manufacture	2018
Top speed	120 mph
0 - 60 mph	10.4 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Life y 1	
Date	2021-06-04
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-01-31
MOT pass rate	100 %
MOT passed	3
Failed MOT tests	0
Total advice items	14
Total items failed	0

MOT #3	2024-02-01 11:19
MOT test number	619032695977
Result	✓ Passed
Next expiry date	2025-01-31

MOT #2		2022-06-28 11:59
MOT test i	number	241977187123
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



Advice

Advice

YD18JKO report date: 2024-03-29

MOT #1 2021-02-10 16:02

MOT test number 750496831461 Result Passed **Advice** Offside Front Tyre slightly damaged/cracking or perishing slight cracking in tread (5.2.3 (d) (ii)) **Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords small cuts in tread (5.2.3 (d) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing slight cracking in tread (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords small cuts in tread (5.2.3 (d) (i)) Advice Nearside Front Tyre slightly damaged/cracking or perishing slight cracking in tread (5.2.3 (d) (ii))

(5.2.3 (d) (i))

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords small cuts in tread

Nearside Rear Tyre slightly damaged/cracking or perishing slight cracking in tread (5.2.3 (d) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords small cuts in tread (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory		
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		A

manage and the same and the sam		

	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-03-31
Last registration	2024-02-01
Complete history	See info



Registration #1	2018-03-31	27 mi
Registration #2	2021-02-10	12.451 mi
Registration #3		11.177 es
Registration #4		77,777 66
Registration #5		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	78%
Safety systems	59%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1680 mm
Length	4550 mm
Wheel base	2700 mm
Kerb weight	1499 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	PE 31221616

CarCheck.co.uk page 11/11