



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO TSI
Colour	White
Year of manufacture	2010
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



**Internet history****Entry 2**

Date	2022-03-09
Pictures	15
Listing price	View report

source: cargurus.co.uk**Entry 1**

Date	2021-06-24
Pictures	1
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-05
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	38
Total items failed	22



MOT #14	2024-04-17 14:42
MOT test number	699107811174
Result	✖ Failed

Fail Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn on edge (5.2.3 (e))

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Rear Narrow tyre stretched to fit wide wheel but correctly seated on the wheel rim

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Coolant leak

Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on edge (5.2.3 (e))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Fail Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition All silencers removed (8.1.1 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Headlamp aim too low (4.1.2 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Narrow tyre stretched to fit wide wheel but correctly seated on the wheel rim

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #132023-04-06 14:27

MOT test number737275553099

Result		✓ Passed
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall damage (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive Multiple (8.4.1 (a) (i))	
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall damage (5.2.3 (d) (ii))	
Advice	Nearside Front Play in shock absorber	
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	

**MOT #12**

2023-03-29 09:50

MOT test number

611390255125

Result

✗ Failed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Play in shock absorber**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Fail** Parking brake lever defective so that it cannot be satisfactorily operated Excessively tight to pull on (1.1.6 (d))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Headlamp levelling device inoperative (4.1.5 (a))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall damage (5.2.3 (d) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall damage (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive Multiple (8.4.1 (a) (i))**MOT #11**

2022-03-31 11:57

MOT test number

183116769068

Result

✓ Passed



MOT #10	2021-07-23 11:24
----------------	------------------

MOT test number	345022249665
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2020-07-24 12:02
---------------	------------------

MOT test number	374626282596
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2019-07-15 12:01
---------------	------------------

MOT test number	841955597348
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2018-07-26 09:37
---------------	------------------

MOT test number	189723519630
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2017-06-14 11:49
---------------	------------------

MOT test number	176533945791
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-05-13 07:51
---------------	------------------

MOT test number	103560088818
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Items removed from drivers view
---------------	---------------------------------

Advice	Undertrays fitted
---------------	-------------------

**MOT #4** 2015-05-05 14:37**MOT test number** 215235925169**Result** ✓ Passed

- Notice** Items removed from driver's view prior to test
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Rear tyres worn inner edges & cracking

MOT #3 2014-04-23 15:04**MOT test number** 987523214193**Result** ✓ Passed

- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #2 2013-05-22 11:08**MOT test number** 356522343111**Result** ✓ Passed

- Notice** Items removed from driver's view prior to test
- Notice** Under-trays fitted obscuring some underside components



MOT #1 2013-05-21 14:36

MOT test number 418461943185

Result ✗ Failed

- Fail** Front registration plate delaminated (6.3.1d)
- Notice** Items removed from driver's view prior to test
- Fail** Offside Rear coil spring incomplete (2.4.C.1a)
- Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✗
MOT
Expired:
5 April 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	MA10DXG
Plate since	2019-03-29
Current registration	MA10DXG
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-21
Last registration	2024-04-17
Complete history	See info



Registration #1	2010-05-21	22 mi
Registration #2	2013-05-21	22.468 mi
Registration #3	2013-05-22	22.468 mi
Registration #4	2014-04-23	26.135 mi
Registration #5	2015-05-05	31.042 mi
Registration #6	2016-05-13	34.772 mi
Registration #7	2017-06-14	41.536 mi
Registration #8	2018-07-26	48.784 mi
Registration #9	2019-07-15	55.865 mi
Registration #10	2020-05-20	55.377 mi
Registration #11	2020-05-20	55.377 mi
Registration #12	2020-05-20	55.377 mi
Registration #13	2020-05-20	55.377 mi
Registration #14	2020-05-20	55.377 mi
Registration #15	2020-05-20	55.377 mi
Registration #16	2020-05-20	55.377 mi
Registration #17	2020-05-20	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1319 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CAX 550962