





report date: 2024-03-29

### General information

Make	RENAULT
Model	CLIO DYNAMIQUE S NAV DCI
Colour	Black
Year of manufacture	2018
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	80.7 mpg
Consumption extra urban	91.1 mpg
Consumption combined	85.6 mpg
CO2 emission	85 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

### MOT history

MOT expiry date	2024-12-19
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	18
Total items failed	1

MOT #7	2023-12-05 11:25
MOT test number	321312738664
Result	<b>✓</b> Passed
Next expiry date	2024-12-19
Advice Parking brake low reserve travel	

MOT #6	2023-12-05 11:25
MOT test number	474741017151
Result	<b>X</b> Failed
Advice Parking brake low reserve travel	
Pass with rectification Windscreen washer provides insufficient washer	liquid (3.5 (a))

MOT #5		2022-12-10 11:03
MOT test	number	709882255079
Result		<b>✓</b> Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
<b>Advice</b> requires a	Offside Rear Service brake requirements only just met. It would appear that djustment or repair $(1.2.1 (c))$	t the braking system

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT #4** 2022-12-10 09:24

**MOT test number** 938749052690

**Result** X Failed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Service brake requirements only just met. It would appear that the braking system

requires adjustment or repair (1.2.1 (c))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #3 2021-12-20 11:20

**MOT test number** 286424968461

Result \rightarrow Passed

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Undertrays fitted

Advice Nearside Front track rod end dust cover slightly deteriorated

**MOT #2** 2020-12-16 11:06

**MOT test number** 628446385750

Result \( \sqrt{Passed} \)

Advice Offside Front Suspension arm ball joint has slight play lower ball joint has slight play (5.3.4 (a) (i))

MOT #1 2020-12-15 15:57

**MOT test number** 203024375668

Result X Failed

**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm ball joint has slight play lower ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	19 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	D
First licence fee (12 months)	£ 130,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



late since

Plate since

MA18LKP

report date: 2024-03-29

Owner history		
For how long did the current and previous owner(s) have this RENAULT? How many own have? Check it in the premium report and see all owner registrations. Download the ful		IAULT
*********		
***************************************		
************		
*********		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
***************************************		
Plate changes	More info	>
See in this check if this RENAULT had different number plates.		
Number of plates		

More info >

EXCESS

CarCheck.co.uk page 8/11



MA18LKP report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-19
Last registration	2023-12-05
Complete history	See info



Registration #1	2018-04-19	18 mi
Registration #2	2020-12-15	66.410 mi
Registration #3	2020-12-16	66.410 mi
Registration #4		11.777 es
Registration #5	2021-12-20	77.006 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 ea
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

### Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1732 mm
Height	1448 mm
Length	4063 mm
Wheel base	2589 mm
Kerb weight	1090 kg
Max. allowed weight	1695 kg

# Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles 2

Engine number R294048