



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Silver
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-10-02
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	25
Total items failed	6

MOT #18	2023-10-03 12:42
---------	------------------

MOT test number	962977726559
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-05
------------------	------------

- Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Play in steering rack inner joint(s)
- Minor

Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Power steering component has slight seepage from a component Rack (2.1.5 (a))
- Minor

Offside Side repeater insecure (4.4.1 (c) (i))

**MOT #17**

2023-10-03 12:42

**MOT test number**

768788314419

**Result****✗ Failed****Pass with rectification** Offside Rear Inner Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Nearside Rear Outer Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Side repeater insecure (4.4.1 (c) (i))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Power steering component has slight seepage from a component Rack (2.1.5 (a))**MOT #16**

2022-10-03 14:41

**MOT test number**

680219843052

**Result****✓ Passed****Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2021-10-06 15:04

**MOT test number**

124164099543

**Result****✓ Passed**

**MOT #14** 2021-09-28 13:05**MOT test number** 115958096561**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn rearward (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension arm pin or bush excessively worn rearward (5.3.4 (a) (i))**MOT #13** 2020-12-16 12:20**MOT test number** 159707034596**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2019-12-09 09:13**MOT test number** 791750648748**Result** ✓ Passed**MOT #11** 2018-12-21 08:29**MOT test number** 687213547836**Result** ✓ Passed**MOT #10** 2017-12-27 11:04**MOT test number** 391105899861**Result** ✓ Passed**MOT #9** 2016-12-30 10:59**MOT test number** 827631481338**Result** ✓ Passed

**MOT #8** 2016-05-24 14:05**MOT test number** 945646113874**Result** ✓ Passed**MOT #7** 2016-05-24 14:05**MOT test number** 637195445938**Result** ✗ Failed

**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6** 2015-06-19 09:54**MOT test number** 165810875153**Result** ✓ Passed**MOT #5** 2014-06-28 09:17**MOT test number** 358479774116**Result** ✓ Passed

**Notice** Nail in nearside rear tyre

**MOT #4** 2013-06-01 10:36**MOT test number** 757492653121**Result** ✓ Passed**MOT #3** 2012-05-22 11:55**MOT test number** 458333942166**Result** ✓ Passed**MOT #2** 2011-05-25 11:30**MOT test number** 588195641124**Result** ✓ Passed



MOT #1	2010-05-28 12:17
MOT test number	730278540134
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
5 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	5 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-25
Last registration	2023-10-03
Complete history	<a href="#">See info</a>



Registration #1	2007-05-25	20 mi
Registration #2	2010-05-28	18.140 mi
Registration #3	2011-05-25	23.024 mi
Registration #4	2012-05-22	28.274 mi
Registration #5	2013-06-01	33.325 mi
Registration #6	2014-06-28	38.880 mi
Registration #7	2015-06-19	44.617 mi
Registration #8	2016-05-24	45.945 mi
Registration #9	2016-05-24	45.945 mi
Registration #10	2016-12-30	46.524 mi
Registration #11	2016-12-30	46.524 mi
Registration #12	2016-12-30	46.524 mi
Registration #13	2016-12-30	46.524 mi
Registration #14	2016-12-30	46.524 mi
Registration #15	2016-12-30	46.524 mi
Registration #16	2016-12-30	46.524 mi
Registration #17	2016-12-30	46.524 mi
Registration #18	2016-12-30	46.524 mi
Registration #19	2016-12-30	46.524 mi
Registration #20	2016-12-30	46.524 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1376 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	70590