





report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ HDI GT
Colour	Blue
Year of manufacture	2011
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-12

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT I	nistory
-------	---------

MOT expiry date	2024-06-24
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	10
Total items failed	6

MOT #14	2023-06-12 14:21
MOT test number	926556495283
Result	✓ Passed
Next expiry date	2024-06-24

MOT #13	2022-06-01 14:15
MOT test number	975762840851
Result	✓ Passed

MOT #12	2022-06-01 09:24
MOT test number	588384913643
Result	X Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #11		2021-06-25 15:43
MOT test	number	701968926341
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Fluid leak, but not excessive engine coolant leak (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2020-06-17 13:14 **MOT** test number 380123238718 Result ✓ Passed **Advice** Nearside headlamp loose **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9

MOT test number

Fesult

Advice Child Seat fitted not allowing full inspection of adult belt 1 x

2019-05-29 11:21

575246274475

✓ Passed

 MOT #8
 2018-06-01 12:21

 MOT test number
 753549519839

 Result
 ✓ Passed

MOT #7

MOT test number

S50717156878

Result

Pass with rectification

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6

MOT test number

860616156706

Result

✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

 MOT #5
 2017-12-05 13:26

 MOT test number
 308986274568

 Result
 X Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #4 2016-12-12 11:02

MOT test number 121743918284

Result ✓ Passed

MOT #3 2016-12-12 11:02

MOT test number 144414903626

Result X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2015-09-15 10:01

MOT test number 780212662176

Advice Emissions too clean to register

MOT #1 2014-09-24 09:29

MOT test number 837927464273

Result
✓ Passed

CarCheck.co.uk page 5/12



SK61PKC report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



SK61PKC report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
THE STATE OF THE S	

THEFERENCE TO THE PARTY OF THE	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



SK61PKC report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-30
Last registration	2023-06-12
Complete history	See info



Registration #1	2011-09-30	27 mi
Registration #2	2014-09-24	11.137 mi
Registration #3	2015-09-15	15.823 mi
Registration #4	2016-12-12	19.537 mi
Registration #5	2016-12-12	19.537 mi
Registration #6	2017-12-05	42.242 mi
Registration #7	2017-12-06	42.242 mi
Registration #8	2018-06-01	53.554 mi
Registration #9		11.777 es
Registration #10		10 100 au
Registration #11		11.777 mi
Registration #11 Registration #12		10.777 es
		11.777 es 11.777 es 11.777 es
Registration #12		10.707 esc 10.707 esc 10.707 esc 10.707 esc
Registration #12 Registration #13		10.777 es 10.777 es 10.777 es 10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1445 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

DYXR4007019