



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S
Colour	Black
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-17
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-02
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	28
Total items failed	14

MOT #17	2023-07-19 11:45
MOT test number	243828556339
Result	✓ Passed
Next expiry date	2024-08-02
Advice	Slight underbody surface rust.
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2022-07-20 12:00
MOT test number	295661967656
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive gearbox (8.4.1 (a) (i))

**MOT #15**

2022-07-20 09:23

MOT test number

554859075431

Result

✗ Failed

Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #14**

2021-08-03 08:11

MOT test number

212300722218

Result

✓ Passed

MOT #13

2021-08-02 14:03

MOT test number

881480914094

Result

✗ Failed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**MOT #12**

2020-11-11 11:15

MOT test number

421290891321

Result

✓ Passed

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear at rear section (1.1.11 (c))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2019-11-18 15:40**MOT test number** 924102717542**Result** ✓ Passed**MOT #10** 2018-11-15 15:06**MOT test number** 602998223847**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #9** 2018-11-14 12:24**MOT test number** 135416387981**Result** ✗ Failed**Advice** Items removed from driver's view prior to test hanging from mirror**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Front Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Rear Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))**MOT #8** 2017-11-22 12:25**MOT test number** 173715594804**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #7** 2017-11-22 12:24**MOT test number** 630188597045**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2016-11-19 14:28**MOT test number** 841119372459**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2015-11-23 13:07**MOT test number** 823630849159**Result** ✓ Passed**Advice** Rear both tyres perishing slightly**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2015-11-21 15:07**MOT test number** 736831818739**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Rear both tyres perishing slightly**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2014-11-05 10:05**MOT test number** 426779604319**Result** ✓ Passed



MOT #2	2013-10-15 09:14
MOT test number	508318183290
Result	✓ Passed
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1	2013-10-02 12:22
MOT test number	175415173259
Result	✗ Failed
Fail	Parking brake lever has no reserve travel (3.1.6b)
Fail	Nearside Rear Road wheel bead rim badly distorted (4.2.A.1a)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-11-12
Last registration	2023-07-19
Complete history	See info



Registration #1	2010-11-12	11 mi
Registration #2	2013-10-02	17.152 mi
Registration #3	2013-10-15	17.189 mi
Registration #4	2014-11-05	22.958 mi
Registration #5	2015-11-21	30.300 mi
Registration #6	2015-11-23	30.300 mi
Registration #7	2016-11-19	37.653 mi
Registration #8	2017-11-22	43.268 mi
Registration #9	2017-11-22	43.268 mi
Registration #10	2018-11-14	51.573 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1040 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1308800