





report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-23

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-27
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	25
Total items failed	3

MOT #12	2023-11-28 11:14
MOT test number	836187735491
Result	✓ Passed
Next expiry date	2024-11-27

MOT #11	2023-11-27 17:14
MOT test number	354594355577
Result	X Failed
Fail Offside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))	

MOT #10	2022-06-09 07:47
MOT test number	222014664366
Result	✓ Passed

MOT #9	2021-08-03 12:40
MOT test number	402518253772
Result	✓ Passed

MOT #8	2021-08-03 12:40
MOT test number	408052395291

Result X Failed

Pass with rectification Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

CarCheck.co.uk page 3/12



MOT #7 2020-11-26 13:45

MOT test number 757335500322

Result \rightarrow Passed

Advice Engine cover fitted

MOT #6 2019-11-08 09:14

MOT test number 300119243074

Result ✓ Passed

Advice Engine cover fitted

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Central stop lamp inop.

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-11-08 09:14

MOT test number 722008701397

Result X Failed

Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice

(i))

Advice Engine cover fitted

Central stop lamp inop.

CarCheck.co.uk page 4/12



Advice

Advice

Engine cover fitted

LL62YNR

report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Items removed from driver's view prior to test

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #3
 2017-11-23 11:26

 MOT test number
 202245186590

 Result
 ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Nearside Front tyre worn on outer edge

Engine cover fitted

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Items removed from driver's view prior to test

MOT #2 2016-11-25 10:55

MOT test number 536324221307

Result

Advice Nearside Front tyre worn on outer edge

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front tyre worn on inner edge

Advice Spanner lamp illuminated

Advice Items removed from driver's view prior to test

CarCheck.co.uk page 5/12



MOT #1 2015-11-02 14:54

MOT test number 657903375098

CarCheck.co.uk page 6/12



LL62YNR

report date: 2024-03-29

Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Type	

Damage 2	
Date	
Category	





Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Mumber of plates	,
Current registration	UK NE
Plate since	
Current registration	AIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-11-30
Last registration	2023-11-28
Complete history	See info



Registration #1	2012-11-30	28 mi
Registration #2	2015-11-02	30.519 mi
Registration #3	2016-11-25	40.304 mi
Registration #4	2017-11-23	50.561 mi
Registration #5	2018-11-23	59.958 mi
Registration #6	2019-11-08	68.206 mi
Registration #7	2019-11-08	68.206 mi
Registration #8		77.777 440
Registration #9		77.777 46
Registration #10		77.777 440
Registration #11		71.777 46
Registration #12		77.777 460
Registration #13		11.177 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1761 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172829K

CarCheck.co.uk page 12/12