



NL56KLE

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SE
Colour	Blue
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg



**MOT history**

MOT #13	2019-03-09 13:03
MOT test number	122870575175
Result	✓ Passed
Next expiry date	2020-03-08
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12	2018-02-14 17:06
MOT test number	759373350875
Result	✓ Passed

MOT #11	2016-09-01 07:52
MOT test number	604921401902
Result	✓ Passed
Advice Amber parking brake light on	

MOT #10	2016-08-31 12:24
MOT test number	426185925910
Result	✗ Failed
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Amber parking brake light on	
Fail Offside Front Steering arm has relative movement at its fixings (2.2.B.1h)	
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)	

MOT #9	2015-09-18 08:27
MOT test number	636566102096
Result	✓ Passed

**MOT #8** 2014-09-22 09:35**MOT test number** 228985164216**Result** ✓ Passed**MOT #7** 2013-09-16 14:22**MOT test number** 828929053242**Result** ✓ Passed**MOT #6** 2013-09-13 09:13**MOT test number** 319246953475**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Electronic parking brake warning indicates a malfunction (3.1.7)**Notice** Offside front track rod worn**MOT #5** 2012-09-04 16:01**MOT test number** 339868742253**Result** ✓ Passed**Notice** Nearside rear tyre has unevenly worn on the inside edge**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2011-09-19 17:27**MOT test number** 398192661236**Result** ✓ Passed

**MOT #3** 2011-09-15 13:01**MOT test number** 818808051230**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Fail** Offside Steering arm has relative movement at its fixings (2.2.B.1h)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-09-08 14:46**MOT test number** 211221250260**Result** ✓ Passed**MOT #1** 2009-09-15 15:11**MOT test number** 260068159245**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 NL56KLE
Plate since	2019-06-29
Current registration	 NL56KLE
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2006-09-13
Last registration	2019-03-09
Complete history	See info



Registration #1	2006-09-13	28 mi
Registration #2	2009-09-15	51.783 mi
Registration #3	2010-09-08	73.141 mi
Registration #4	2011-09-15	93.193 mi
Registration #5	2011-09-19	93.193 mi
Registration #6	2012-09-04	101.541 mi
Registration #7	2013-09-13	110.798 mi
Registration #8	2019-03-09	110.798 mi
Registration #9	2019-03-09	110.798 mi
Registration #10	2019-03-09	110.798 mi
Registration #11	2019-03-09	110.798 mi
Registration #12	2019-03-09	110.798 mi
Registration #13	2019-03-09	110.798 mi
Registration #14	2019-03-09	110.798 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1616 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BKC 702422