



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D5 R-DESIGN LUX NAV AWD
Colour	Black
Year of manufacture	2014
Top speed	121 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 3

Date	2023-03-22
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 2


Date	2021-06-24
Pictures	26
Listing price	<a href="#">View report</a>



source: [heycar.co.uk](#)

Entry 1

Date	2021-05-27
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-30
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	17
Total items failed	3

MOT #8	2024-03-27 16:07
--------	------------------

MOT test number	862547298375
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-30
------------------	------------

- AdviceTyre sealant expired
- AdviceItems removed from driver's view prior to test
- AdviceFront Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceNearside number plate lamp dim
- MinorWindscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- AdviceNearside Front suspension bottom ball joint weeping grease

**MOT #7**

2024-03-27 09:52

**MOT test number**

745404804222

**Result****✗ Failed**

- Advice** Nearside Front suspension bottom ball joint weeping grease
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Fail** Offside Front Seat belt not functioning as intended will not release under tension (7.1.2 (c))
- Advice** Tyre sealant expired
- Fail** Offside Hazard warning lamps inoperative repeater (4.4.1 (e))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside number plate lamp dim
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #6**

2023-03-31 08:12

**MOT test number**

196507006316

**Result****✓ Passed****MOT #5**

2022-04-16 07:41

**MOT test number**

702719446086

**Result****✓ Passed****MOT #4**

2021-05-07 14:16

**MOT test number**

266081760758

**Result****✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #3	2019-07-23 10:43
MOT test number	807247898645
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2	2018-05-10 09:16
MOT test number	646628597782
Result	✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt

MOT #1	2017-04-04 12:07
MOT test number	318145856829
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
30 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	30 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>KN14UPP</b>
Plate since	2019-09-29
Current registration	<b>KN14UPP</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2024-03-27
Complete history	<a href="#">See info</a>



Registration #1	2014-03-31	22 mi
Registration #2	2017-04-04	19.840 mi
Registration #3	2018-05-10	26.605 mi
Registration #4	2019-07-23	33.760 mi
Registration #5	2021-05-07	46.346 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2023-05-20	65.277 mi
Registration #8	2024-05-20	75.277 mi
Registration #9	2025-05-20	85.277 mi
Registration #10	2026-05-20	95.277 mi
Registration #11	2027-05-20	105.277 mi
Registration #12	2028-05-20	115.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1862 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1522159