





report date: 2024-03-29

#### General information

Make	AUDI
Model	RS4 RS4 QUATTRO
Colour	Black
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	4.9 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	415 BHP
Max. torque	430 Nm at 5.500 rpm
Engine capacity	4.163 cc
Cylinders	8
Fuel type	Petrol
Consumption city	13.2 mpg
Consumption extra urban	29.4 mpg
Consumption combined	20.3 mpg
CO2 emission	334 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-29


## Internet history

#### Entry 2

Date 2022-05-18


Pictures 37

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1


Date 2022-01-26


Pictures 37

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

#### MOT history

MOT expiry date	2023-03-28
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	11
Total items failed	6

MOT #15	2022-03-29 09:08
MOT test number	407559855033
Result	✓ Passed
Next expiry date	2023-03-28

MOT #14	2022-03-23 10:15
MOT test number	650989822043
Result	<b>X</b> Failed
Advice Nearside Front Upper Suspension arm pin or bush worn but not re Rear arm (5.3.4 (a) (i))  Fail Nearside Side repeater incorrect colour (4.4.3 (a))	esulting in excessive movement

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Rear arm (5.3.4 (a) (i))

MOT #13	2021-06-10 09:29
MOT test number	589607526710
Result	✓ Passed
MOT #12	2020-06-04 14:07
MOT test number	960788262149
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #11** 2020-06-04 14:07

**MOT test number** 633595662450

Result X Failed

Pass with rectification Nearside Rear Registration plate lamp does not illuminate simultaneously with

the position lamps (4.7.2 (a))

**MOT #10** 2019-07-03 11:17

**MOT test number** 861378511639

**Result** ✓ Passed

MOT #9 2017-04-26 09:23

**MOT test number** 745763762708

**Result** ✓ Passed

**MOT #8** 2017-04-26 09:23

MOT test number 148681776363

**Result** X Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**Pass with rectification** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

MOT #7 2016-04-28 09:37

**MOT test number** 419432320974

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5

MOT test number

899343013347

Result

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

 MOT #4
 2012-10-31 09:12

 MOT test number
 555245002341

 Result
 ✓ Passed

 MOT #3
 2011-09-29 14:29

 MOT test number
 516132071224

 Result
 ✓ Passed

MOT test number

Result

MOT #2

MOT test number

MOT test number

341111010231

Result

Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice

Offside Front Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2009-08-01 11:13

**MOT test number** 782593219268

**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Front brake disc slightly scored (3.5.1h)

CarCheck.co.uk page 6/13



K666RSA report date: 2024-03-29

#### Tax & MOT check



Tax expired: 10 December 2022

# **Х** мот

Expired: 28 March 2023

Tax status	Expired at 10 December 2022
Days left	507 days too late
MOT expiry date	28 March 2023
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did Check it in the premium report and see all owner registrations. Download the full report if	
THE PARTY OF THE P	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	AK UK
Plate since	
Current registration	NIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



K666RSA
report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-07-25
Last registration	2022-03-29
Complete history	See info



Registration #1	2006-07-25	17 mi
Registration #2	2009-08-01	18.949 mi
Registration #3	2010-07-30	24.363 mi
Registration #4	2011-09-29	30.050 mi
Registration #5	2012-10-31	36.967 mi
Registration #6	2013-11-09	46.342 mi
Registration #7	2016-04-19	58.733 mi
Registration #8	2016-04-28	58.734 mi
Registration #9	2017-04-26	64.064 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		19.777 es

More info >

CarCheck.co.uk page 12/13



K666RSA report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1814 mm
Height	1391 mm
Length	4555 mm
Wheel base	2650 mm
Kerb weight	1845 kg
Max. allowed weight	2305 kg

## Additional information

Fuel tank capacity	63 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13