



PEUGEOT



DLIOFKW


report date: 2024-03-29

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Red
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-25
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-11
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	26
Total items failed	5

MOT #16	2023-07-07 13:52
MOT test number	823200997738
Result	✓ Passed
Next expiry date	2024-07-11

MOT #15	2023-07-07 10:11
MOT test number	497563312804
Result	✗ Failed
Fail	Offside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))

MOT #14	2022-07-08 11:01
MOT test number	420889158175
Result	✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #13**

2021-07-12 12:03

**MOT test number**

871936052450

**Result**

✓ Passed

**Advice**

Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Front Exhaust has a minor leak of exhaust gases flexible pipe (6.1.2 (a))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement cut (5.3.4 (a) (i))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice**

Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2020-10-27 15:29

**MOT test number**

531482102332

**Result**

✓ Passed

**MOT #11**

2019-10-25 15:56

**MOT test number**

447661143567

**Result**

✓ Passed

**MOT #10**

2018-10-23 11:46

**MOT test number**

987778434971

**Result**

✓ Passed

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**Advice**

Front Tyre worn close to legal limit/worn on edge n/s &amp; o/s (5.2.3 (e))

**MOT #9**

2018-10-23 10:57

**MOT test number**

349855923606

**Result****✗ Failed****Advice**

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**Fail**

Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Front Tyre worn close to legal limit/worn on edge n/s &amp; o/s (5.2.3 (e))

**MOT #8**

2017-10-13 13:18

**MOT test number**

703580678417

**Result****✓ Passed****Advice**

Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**Advice**

Offside Rear Nail in tyre

**MOT #7**

2017-10-10 13:57

**MOT test number**

133026399471

**Result****✗ Failed****Fail**

Offside Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

**Advice**

Offside Rear Nail in tyre

**Fail**

Nearside Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice**

Central Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**MOT #6**

2016-10-07 09:27

**MOT test number**

362557449069

**Result****✓ Passed**

**MOT #5** 2015-10-28 17:03**MOT test number** 266488003843**Result** ✓ Passed**Advice** LED's out in high level stop light**MOT #4** 2015-10-28 09:18**MOT test number** 862859228037**Result** ✗ Failed**Advice** LED's out in high level stop light**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #3** 2015-06-11 15:29**MOT test number** 989862465171**Result** ✓ Passed**MOT #2** 2014-06-20 15:27**MOT test number** 318671574161**Result** ✓ Passed**MOT #1** 2013-06-24 12:34**MOT test number** 508765873128**Result** ✓ Passed**Notice** Noise on o/s and n/s front top shocker mounts**Notice** O/s and n/s rear tyres worn on edges**Notice** Oil leak



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
11 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	11 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>DL10FKW</b>
Plate since	2019-03-29
Current registration	<b>DL10FKW</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-07-07
Last registration	2023-07-07
Complete history	<a href="#">See info</a>



Registration #1	2010-07-07	25 mi
Registration #2	2013-06-24	18.822 mi
Registration #3	2014-06-20	22.350 mi
Registration #4	2015-06-11	26.456 mi
Registration #5	2015-10-28	28.738 mi
Registration #6	2015-10-28	28.738 mi
Registration #7	2016-10-07	35.138 mi
Registration #8	2017-10-10	40.520 mi
Registration #9	2017-10-13	40.520 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi
Registration #18	2019-05-29	55.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1350 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

**Engine number**

FJBD0799390