



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LOOK
Colour	Silver
Year of manufacture	-
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-30
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #20</b>	2022-10-12 12:52
<b>MOT test number</b>	132057930404
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-10-12
<b>Advice</b>	Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

<b>MOT #19</b>	2021-10-13 12:55
<b>MOT test number</b>	116397779114
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Fuel tank strap corroded/broken
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #18**

2021-10-12 10:50

**MOT test number**

400678092837

**Result****✗ Failed**

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Fuel tank strap corroded/broken
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Headlamp aim projected beam image is obviously incorrect offside & nearside (4.1.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #17**

2021-09-23 11:52

**MOT test number**

175703669244

**Result****✗ Failed**

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Central Rear Seat belt anchorage loose Rear Seat back does not lock in position - is top mounting for rear central belt (7.1.1 (b))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Central Exhaust has a major leak of exhaust gases Exhaust holed around central mounting bracket (6.1.2 (a))
- MAJOR** Central Rear Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #16** 2020-09-28 09:52**MOT test number** 634518136049**Result** ✓ Passed**MOT #15** 2020-09-28 09:52**MOT test number** 303649075793**Result** ✗ Failed**Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))**MOT #14** 2019-08-27 10:27**MOT test number** 505165242387**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play Bottom ball joint (5.3.4 (a) (i))**Advice** Items removed from driver's view prior to test Items left on passenger seat**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases Front join under vehicle (6.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Tyre perishing/ cracking (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive Gearbox oil leak (8.4.1 (a) (i))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated Dust cover starting to split (5.3.4 (b) (i))**Advice** Oil leak, but not excessive Engine oil leak (8.4.1 (a) (i))

**MOT #13**

2019-08-27 10:27

**MOT test number**

374536940953

**Result**

✗ Failed

**Advice** Exhaust has a minor leak of exhaust gases Front join under vehicle (6.1.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive Gearbox oil leak (8.4.1 (a) (i))**Advice** Items removed from driver's view prior to test Items left on passenger seat**Pass with rectification** Offside Headlamp aim too low and too far to the left. (4.1.2 (a))**Advice** Oil leak, but not excessive Engine oil leak (8.4.1 (a) (i))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated Dust cover starting to split (5.3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play Bottom ball joint (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Tyre perishing/ cracking (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))**MOT #12**

2018-08-28 08:48

**MOT test number**

718706735523

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On limit (5.2.3 (e))**Advice** Play in steering rack inner joint(s)

**MOT #11** 2017-08-24 09:58**MOT test number** 617680756594**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2017-08-24 09:58**MOT test number** 148689825595**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #9** 2016-09-09 14:54**MOT test number** 443964672052**Result** ✓ Passed**MOT #8** 2015-06-29 10:00**MOT test number** 638320285193**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #7** 2014-07-02 09:09**MOT test number** 695403984129**Result** ✓ Passed

**MOT #6** 2014-06-25 12:40**MOT test number** 557606274101**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #5** 2013-06-20 14:40**MOT test number** 297761773177**Result** ✓ Passed**MOT #4** 2012-06-15 11:02**MOT test number** 576927862156**Result** ✓ Passed**Advice** Nearside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #3** 2012-06-15 10:00**MOT test number** 617647262188**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #2** 2011-06-27 11:12**MOT test number** 376358971117**Result** ✓ Passed**Notice** N/s/f tyre wearing on outside edge**MOT #1** 2010-06-30 11:06**MOT test number** 732581180124**Result** ✓ Passed





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-22
Last registration	2022-10-12
Complete history	<a href="#">See info</a>



Registration #1	2007-06-22	20 mi
Registration #2	2010-06-30	9.835 mi
Registration #3	2011-06-27	14.367 mi
Registration #4	2012-06-15	17.765 mi
Registration #5	2012-06-15	17.765 mi
Registration #6	2013-06-20	23.525 mi
Registration #7	2014-06-25	29.723 mi
Registration #8	2014-07-02	29.810 mi
Registration #9	2015-06-29	32.948 mi
Registration #10	2016-09-09	35.859 mi
Registration #11	2017-08-24	57.445 mi
Registration #12	2018-06-20	58.337 mi
Registration #13	2018-06-20	58.337 mi
Registration #14	2018-06-20	58.337 mi
Registration #15	2018-06-20	58.337 mi
Registration #16	2018-06-20	58.337 mi
Registration #17	2018-06-20	58.337 mi
Registration #18	2018-06-20	58.337 mi
Registration #19	2018-06-20	58.337 mi
Registration #20	2018-06-20	58.337 mi
Registration #21	2018-06-20	58.337 mi
Registration #22	2022-10-12	58.337 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FST65692714