



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN R-LINE TSI S-A
Colour	Black
Year of manufacture	2020
Top speed	126 mph
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	148 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	38.7 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-08
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2024-12-17
MOT pass rate	33 %
MOT passed	1
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #3	2023-12-18 14:34
MOT test number	131077814620
Result	✓ Passed
Next expiry date	2024-12-17
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2	2023-12-18 14:34
MOT test number	437263914922
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))



MOT #1	2023-11-28 14:58
MOT test number	175434507602
Result	✗ Failed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
17 December 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	17 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 CP70AHK
Plate since	2019-03-28
Current registration	 CP70AHK
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2020-12-17
Last registration	2023-12-18
Complete history	See info



Registration #1	2020-12-17	14 mi
Registration #2	2021-11-29	25,377 mi
Registration #3	2023-11-28	40.437 mi
Registration #4	2023-11-29	25,377 mi
Registration #5	2023-12-18	25,377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	84%
Pedestrian	72%
Safety systems	68%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1839 mm
Height	1675 mm
Length	4509 mm
Wheel base	2678 mm
Kerb weight	1512 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	58 l
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	DPCA467686