



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA DYNAMIC
Colour	Blue
Year of manufacture	2006
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	102 Nm at 2.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	133 g/km
CO2 label	E








Internet history

Entry 1

Date	2021-06-11
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-11-20
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	33
Total items failed	11

MOT #20	2022-11-21 17:16
MOT test number	260576232812
Result	✓ Passed
Next expiry date	2023-11-20

MOT #19	2022-11-21 11:57
MOT test number	488054827125
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #18	2021-08-10 11:12
MOT test number	649868058688
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2020-09-01 09:04
MOT test number	689709535006
Result	✓ Passed

**MOT #16** 2019-09-11 14:17**MOT test number** 203195167219**Result** ✓ Passed**MOT #15** 2019-09-10 16:22**MOT test number** 207825680370**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Windscreen wiper not working (3.4 (a))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #14** 2018-08-29 15:55**MOT test number** 139551680488**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Exhaust back box deteriorated**MOT #13** 2017-08-12 10:40**MOT test number** 304849846466**Result** ✓ Passed**Advice** Both Front Anti Roll Bar Drop Links Have Play In Them**Advice** Nail In O/S/R Tyre**Advice** Spare Tyre Defective**Advice** Radiator Leaking Slightly**Advice** Exhaust System Corroded**Advice** N/S/R Seat Belt Damaged

**MOT #12**

2017-08-12 09:43

MOT test number

446904727504

Result

✗ Failed

Advice Spare Tyre Defective**Advice** Radiator Leaking Slightly**Advice** Exhaust System Corroded**Advice** N/S/R Seat Belt Damaged**Advice** Both Front Anti Roll Bar Drop Links Have Play In Them**Advice** Nail In O/S/R Tyre**Fail** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**MOT #11**

2016-09-03 09:40

MOT test number

492470021447

Result

✓ Passed

Advice Suspension arm rubber bush deteriorated but not resulting in excessive movement Both front lower wishbones rear bush (2.4.G.2)**Advice** Offside front shock absorber casing corroded**Advice** Offside Front Upper Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Corrosion to rear exhaust**MOT #10**

2015-11-16 11:29

MOT test number

411575187021

Result

✓ Passed

Advice Nearside Rear Seat belt stitching slightly frayed (5.2.2b)**Advice** Offside Front Upper Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #9** 2014-11-24 12:26**MOT test number** 478898424349**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear exhaust silencer poor condition not blowing**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-11-26 14:59**MOT test number** 369780633306**Result** ✓ Passed**MOT #7** 2012-11-12 12:24**MOT test number** 105597812358**Result** ✓ Passed**MOT #6** 2012-11-08 17:14**MOT test number** 839123612340**Result** ✗ Failed**Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**Fail** Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #5** 2012-02-10 14:46**MOT test number** 149431442493**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #4** 2012-02-10 10:08**MOT test number** 108741442436**Result** ✗ Failed**Fail** Stop lamp not working (1.2.1b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2011-02-05 09:52**MOT test number** 445676031046**Result** ✓ Passed**MOT #2** 2010-02-03 12:35**MOT test number** 371624730029**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #1** 2009-02-20 11:33**MOT test number** 291681159084**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 November 2023

✕
MOT

Expired:
20 November 2023

Tax status	Expired at 1 November 2023
Days left	180 days too late
MOT expiry date	20 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-04-27
Last registration	2022-11-21
Complete history	See info



Registration #1	2006-04-27	6 mi
Registration #2	2009-02-20	18.333 mi
Registration #3	2010-02-03	25.050 mi
Registration #4	2011-02-05	31.582 mi
Registration #5	2012-02-10	37.851 mi
Registration #6	2012-02-10	37.851 mi
Registration #7	2012-11-08	42.874 mi
Registration #8	2012-11-12	42.874 mi
Registration #9	2013-11-26	53.635 mi
Registration #10	2014-11-24	61.761 mi
Registration #11	2015-11-16	71.800 mi
Registration #12	2016-11-16	81.839 mi
Registration #13	2017-11-16	91.878 mi
Registration #14	2018-11-16	101.917 mi
Registration #15	2019-11-16	111.956 mi
Registration #16	2020-11-16	121.995 mi
Registration #17	2021-11-16	132.034 mi
Registration #18	2022-11-21	142.073 mi
Registration #19	2023-11-21	152.112 mi
Registration #20	2024-03-28	162.151 mi
Registration #21	2024-03-28	172.190 mi
Registration #22	2024-03-28	182.229 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1589 mm
Height	1578 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	2105 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats 4

Engine number	3439193
---------------	---------