





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM DCI
Colour	White
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2025-03-17
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	22
Total items failed	12

MOT #14	2024-03-18 13:48
MOT test number	973614559449
Result	✓ Passed
Next expiry date	2025-03-17
Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))	

MOT #13 2024-03-13 10:01

MOT test number 945768011922

Result X Failed

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #12	2023-03-07 09:27
MOT test number	480947208110
Result	✓ Passed
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely dete	eriorated (6.1.7 (g) (i))

CarCheck.co.uk page 2/12



Result

LM12YEG
report date: 2024-03-28

× Failed

MOT #11 2022-03-17 11:22

MOT test number 183686651370

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10 2022-03-17 11:22

MOT test number 936556074634

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Pass with rectification Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2021-03-17 10:33

MOT test number 260652978706

CarCheck.co.uk page 3/12



MOT #8 2020-07-02 15:10

MOT test number 920566319348

Result
✓ Passed

MOT #7 2019-04-30 13:58

MOT test number 424303344391

Result

Passed

MOT #6 2019-04-30 08:49

MOT test number 845803531289

Result X Failed

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

MOT #5 2018-04-12 13:52

MOT test number 876751263104

CarCheck.co.uk page 4/12



LM12YEG

report date: 2024-03-28

MOT #4	2018-04-11 15:14
MOT test number	358483454178
Result	× Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no ingress of dirt etc (2.5.C.1a)	longer prevents the
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	

MOT #3	2017-04-28 13:06
MOT test number	754596240598
Result	✓ Passed
MOT #2	2016-04-06 09:20
MOT test number	486733169188
Result	✓ Passed

MOT test	number	486733169188
Result		✓ Passed
MOT #1		2015-05-01 17:01
MOT test	number	719231825170
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	17 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

•		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-04-27
Last registration	2024-03-18
Complete history	See info



Registration #1	2012-04-27	14 mi
Registration #2	2015-05-01	34.086 mi
Registration #3	2016-04-06	44.081 mi
Registration #4	2017-04-28	54.632 mi
Registration #5	2018-04-11	64.518 mi
Registration #6	2018-04-12	64.518 mi
Registration #7	2019-04-30	72.674 mi
Registration #8	2019-04-30	72.674 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		D.277 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1795 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 page 1	12/12

Number of axles 2

Engine number D090924